

EPA-450/3-76-001

March 1976

**RELIABILITY STUDY
OF VAPOR
RECOVERY SYSTEMS
AT SERVICE STATIONS**



**U.S. ENVIRONMENTAL PROTECTION AGENCY
Office of Air Quality and Waste Management
Office of Air Quality Planning and Standards
Research Triangle Park, North Carolina 27711**

EPA-450/3-76-001

**RELIABILITY STUDY
OF VAPOR
RECOVERY SYSTEMS
AT SERVICE STATIONS**

by

R.J. Bryan, L.G. Wayne, and R.L. Norton

**Pacific Environmental Services, Inc.
1930 11th Street
Santa Monica, California 90404**

Contract No. 68-02-1405, Task Order No. 2

EPA Project Officer: Edwin J. Vincent

Prepared for

**ENVIRONMENTAL PROTECTION AGENCY
Office of Air and Waste Management
Office of Air Quality Planning and Standards
Research Triangle Park, North Carolina 27711**

March 1976

This report is issued by the Environmental Protection Agency to report technical data of interest to a limited number of readers. Copies are available free of charge to Federal employees, current contractors and grantees, and nonprofit organizations - as supplies permit - from the Air Pollution Technical Information Center, Environmental Protection Agency, Research Triangle Park, North Carolina 27711; or, for a fee, from the National Technical Information Service, 5285 Port Royal Road, Springfield, Virginia 22161.

This report was furnished to the Environmental Protection Agency by Pacific Environmental Services, Inc., Santa Monica, California 90404, in fulfillment of Contract No. 68-02-1405. The contents of this report are reproduced herein as received from Pacific Environmental Services, Inc. The opinions, findings, and conclusions expressed are those of the author and not necessarily those of the Environmental Protection Agency. Mention of company or product names is not to be considered as an endorsement by the Environmental Protection Agency.

Publication No. EPA-450/3-76-001

USEPA

This is not an official policy and standards document. The opinions, findings, and conclusions are those of the authors and not necessarily those of the United States Environmental Protection Agency. Every attempt has been made to represent the present state of the art as well as subject areas still under evaluation. Any mention of products, or organizations, does not constitute endorsement by the United States Environmental Protection Agency.

ABSTRACT

Pacific Environmental Services, Inc. (PES) conducted a study of the operational reliability of vapor recovery systems at gasoline service stations in San Diego County. This work was performed under EPA Contract No. 68-02-1405, Task Order No. 2. Periodic inspections of vapor recovery systems at twenty-four stations were conducted over the period May through July 1975 to examine the condition of these systems, to determine their operational status, and to check for observable gasoline vapor losses from control equipment. In all, 140 such inspections were made. During these visits, 506 vehicle refuelings were observed and the gasoline vapor capture effectiveness checked at the nozzle-vehicle fillneck interface using a combustible gas analyzer.

The study demonstrated that capture of vapors at the vehicle as determined by the use of a combustible gas analyzer was more effective with vacuum-assisted systems than with vapor-balance systems. Gasoline vapor concentrations exceeding one tenth of the lower explosive limit were detected in fourteen percent of the vehicle refuelings where vacuum-assisted systems were used. The percent of refuelings exceeding the 0.1 LEL criterion among the individual manufacturers ranged from six to eighteen percent. For vapor balance systems, nozzle design strongly influences effectiveness. The number of refuelings where gasoline concentration at balance systems exceeded 0.1 LEL ranged from twenty-nine percent where better fitting nozzles were used to eighty percent where poorer fitting nozzles were used. The effect of greater capture efficiency of vacuum assist systems was offset to some degree by poorer reliability.

The reliability of the vacuum-assisted systems, as determined by the frequency of equipment malfunctions and gasoline vapor leaks at the vapor recovery units and vents, was not good although there were substantial variations in performance depending upon the type of unit and the location. Specifically, there was some evidence of malfunction or vapor loss in eighty-eight percent of the visits to vacuum assist stations. There were, however, four locations which were partially inoperative during the entire period of the study. In these cases, retrofits expected during the planning stages of the project were not accomplished. If these locations are not included in the evaluation, the proportion of visits to vacuum assist stations where hydrocarbon losses or malfunctions were observed becomes eighty-four percent. There were no hydrocarbon losses or equipment malfunctions observed at one location equipped with a direct flame afterburner unit not incorporating intermediate vapor hold-up in a carbon bed or in a vapor holder. Excessive vapors may have been consumed by this unit because of nearly continuous operation possibly resulting from piping leaks. (See Table V).

Vapor capture effectiveness at the nozzle-fill tube interface did not appear to be affected by "self-serve" gasoline delivery. These were very few instances of gasoline spillage during delivery operations. Activated carbon adsorption bed vents appeared to be a minor source of hydrocarbon losses.

No data on quantitative control efficiencies of complete vapor recovery systems were obtained during this study nor can direct inferences be drawn on efficiencies from the information presented.

TABLE OF CONTENTS

| <u>Section</u> | <u>Page</u> |
|--|-------------|
| I. INTRODUCTION | I-1 |
| II. VAPOR RECOVERY SYSTEMS | II-1 |
| A. VAPOR-BALANCE SYSTEMS | II-1 |
| B. VACUUM-ASSIST SYSTEMS | II-1 |
| 1. General | II-1 |
| 2. The Intermark System | II-4 |
| 3. The Process Products System | II-4 |
| 4. The Clean Air Engineering System | II-8 |
| 5. The Environics System | II-8 |
| 6. The Hirt System | II-12 |
| III. METHODS AND EQUIPMENT | III-1 |
| A. THE STUDY PLAN | III-1 |
| B. STATION SELECTION | III-1 |
| C. INSPECTION FORMS | III-2 |
| D. INSPECTION PROCEDURE | III-4 |
| E. EVALUATING OPERATIONAL STATUS | III-4 |
| F. DETECTION OF HYDROCARBON VAPOR LEAKAGE | III-5 |
| G. PERFORMANCE EVALUATION | III-6 |
| IV. RESULTS AND DISCUSSION | IV-1 |
| A. GENERAL | IV-1 |
| B. SYSTEM MALFUNCTIONS | IV-3 |
| C. MEASURED OPERATIONAL PARAMETERS | IV-6 |
| D. HYDROCARBON LOSSES ON FILLING VEHICLE TANKS | IV-11 |
| E. EFFECTIVENESS OF SYSTEMS WHEN OPERATING OPTIMALLY | IV-13 |
| F. EFFECT OF NOZZLE TYPE ON VAPOR LOSSES (WITH VAPOR-BALANCE SYSTEMS) | IV-15 |
| G. EFFECT OF ATTENDANT SERVICE VS. SELF-SERVICE ON VAPOR LOSSES | IV-15 |
| H. EFFECT OF VEHICLE FILLNECK CONFIGURATION ON VAPOR LOSSES | IV-18 |
| I. LIQUID LOSSES IN FILLING VEHICLES | IV-18 |
| J. VAPOR LOSSES THROUGH CARBON CANISTERS | IV-19 |

TABLE OF CONTENTS (continued)

| <u>Section</u> | | <u>Page</u> |
|----------------|---|-------------|
| V. | CONCLUSIONS | V-1 |
| | A. EFFECTIVENESS OF VAPOR RECOVERY SYSTEMS IN CAPTURING HYDROCARBON VAPORS WHEN FILLING VEHICLE TANKS | V-1 |
| | B. OPERATIONAL RELIABILITY OF VAPOR RECOVERY SYSTEMS | V-2 |
| APPENDIX A. | INSPECTION FORMS | A-1 |
| APPENDIX B. | AUTOMOBILES TESTED | B-1 |
| APPENDIX C. | MEASURED OPERATIONAL PARAMETERS | C-1 |
| APPENDIX D. | AUTOMOBILES WITH FILLNECKS POORLY FIT BY NOZZLES | D-1 |
| APPENDIX E. | OBSERVATIONS WITH EPA HYDROCARBON DETECTORS | E-1 |

| <u>Figures</u> | LIST OF FIGURES | <u>Page</u> |
|----------------|---|-------------|
| 1-A. | SCHEMATIC DIAGRAM OF MANIFOLDED BALANCE SYSTEMS . | II-2 |
| 1-B. | SCHEMATIC DIAGRAM OF NON-MANIFOLDED BALANCE SYSTEM | II-2 |
| 2. | SCHEMATIC DIAGRAM OF INTERMARK SYSTEM (MARK I) . | II-5 |
| 3. | SCHEMATIC DIAGRAM OF PROCESS PRODUCTS SYSTEM . . | II-6 |
| 4. | SCHEMATIC DIAGRAM OF CLEAN AIR ENGINEERING SYSTEM (MODEL 5000B). | II-9 |
| 5. | SCHEMATIC DIAGRAM OF ENVIRONICS SYSTEM (MODEL A-3000) | II-11 |
| 6. | SCHEMATIC DIAGRAM OF HIRT SYSTEM | II-13 |

| <u>Tables</u> | LIST OF TABLES | <u>Page</u> |
|---------------|---|-------------|
| I. | FILLING STATIONS SELECTED FOR STUDY | III-3 |
| II. | SUMMARY OF INSPECTIONS | IV-2 |
| III. | FREQUENCY OF OCCURRENCE OF SPECIFIC MALFUNCTIONS AT VACUUM ASSIST STATIONS | IV-4 |
| IV. | FREQUENCY OF CAUSES OF FAILURE TO OPERATE AT VACUUM ASSIST SYSTEMS | IV-5 |
| V. | FREQUENCY OF OCCURRENCE OF SPECIFIC MALFUNCTION BY MANUFACTURER | IV-7 |

TABLE OF CONTENTS (continued)

| <u>Section</u> | | <u>Page</u> |
|----------------|---|-------------|
| VI. | FREQUENCY OF CAUSES OF HYDROCARBON LOSSES AT VACUUM ASSIST STATIONS | IV-8 |
| VII. | FREQUENCIES OF OBSERVED CONCENTRATIONS OF HYDRO- CARBONS AT NOZZLE-FILLNECK INTERFACE BELOW VARIOUS CRITERION VALUES | IV-12 |
| VIII. | DEGREE OF CONTROL ACHIEVED WITH VAPOR-CONTROL STATIONS OPERATING OPTIMALLY | IV-14 |
| IX. | FREQUENCIES OF OBSERVED CONCENTRATIONS OF HYDRO- CARBONS AT NOZZLE-FILLNECK INTERFACE EXCEEDING VARIOUS CRITERION VALUES, WITH DIFFERENT NOZZLES (VAPOR-BALANCE SYSTEMS) | IV-16 |
| X. | VAPOR LOSSES OBSERVED AT SELF-SERVICE AND ATTEN- DANT-SERVICE STATIONS | IV-17 |

I. INTRODUCTION

In the prevention of photochemical oxidant air pollution, control of gasoline vapor displaced during retail marketing operations has been recognized as an important measure. In a pioneering effort, the San Diego Air Pollution Control District promulgated in 1972 regulations requiring the use of vapor recovery systems at gasoline filling stations, to minimize the escape of hydrocarbon vapors to the atmosphere during the delivery of gasoline to individual vehicles. Several manufacturers have devised and marketed systems for this purpose. They are currently in use in the San Diego and San Francisco areas and to a lesser degree in other metropolitan areas of the United States. These are known as Stage II controls although they can be used to assist in controlling vapors during bulk delivery of gasoline to the service station (Stage I control).

As a special task under EPA Contract 68-02-1405, PES has conducted a study of the effectiveness and operational reliability of new and modified vapor-control systems in San Diego County. The objective was to investigate new systems and those which had been modified since the TRW study of 1974^{*}. Most new and modified systems which were in operation were included in the study. A large number of units were in the process of being modified and were shut down. The approach used in this study was to conduct periodic inspections of selected operating systems to determine whether the systems were in proper operating condition and were being properly utilized, and to test for observable hydrocarbon vapor losses from the equipment and from the interface between the dispensing nozzle and the vehicle fillneck during filling operations.

The San Diego County area was chosen for the study because the two principal types of service station vapor recovery equipment, vapor balance and vacuum assist, were in use and available for

^{*}Powell, D.J. and D.E. Hasselmann. "Reliability Observations and Emission Measurements at Gasoline Transfer Vapor Recovery Systems." TRW, Inc., for EPA under Contract 68-02-0235, November 1974.

observation. In vapor balance systems, the vapor laden air from the fuel tank of the vehicle is displaced directly (through tubing) into the vapor space of the underground storage tank. The motive force is supplied by the pressure generated by the dispensed gasoline in the vehicle tank and by the vacuum created in the underground tank by gasoline removal. In vacuum assist systems, displaced vapors from the vehicle fuel tank are captured at the vehicle fillneck by means of an air pump or blower. In the latter type of system, excess vapors are treated in a supplementary control unit. Two types of vapor balance and five types of vacuum assist systems were in use at filling stations selected for the survey. These systems are described in Section II of this report.

This report deals primarily with Stage II vapor recovery. Although some information was gathered on Stage I, the data was not sufficient to be treated in this report. (Stage I vapor recovery deals with underground tank refilling operations, Stage II vapor recovery deals with vehicle refueling operations). Subsequent sections cover methods of investigation and equipment utilized in the study, inspection procedures, study-findings, discussion, and conclusions.

Hydrocarbon breakthrough detectors, supplied by the Environmental Protection Agency, were installed at the outlet of carbon bed adsorption units at six service stations. There were two types of detectors (described in Section III-F below) and three makes of control equipment represented. Thus, each type of detector was installed on each of the three makes of control equipment. The detectors were installed to determine whether hydrocarbon concentrations above a pre-set level in exit gases were discharged from the carbon beds.

Further study of the characteristics and performance of carbon units is to be carried out as part of the same contract. The purpose of the carbon study is to determine the capacity of the

carbon beds and effectiveness of regeneration cycles, and to indicate whether there is a build-up of residual high molecular weight hydrocarbons on the carbon beds. Carbon samples will be taken once each month for about six months and tested to determine:

1. Capacity and retentivity in adsorption of carbon tetrachloride.
2. Hydrocarbon content by thermal analysis.
3. Loading of particular hydrocarbons, by gas chromatography.
4. Bulk density.

As another subtask, costs associated with the various vapor control systems have been determined. Information was obtained from installation contractors, station operators, oil companies, the San Diego Air Pollution Control District, and the office of the San Diego County Assessor. A final report on this subtask was submitted earlier, titled "Cost Data, Vapor Recovery Systems at Service Stations" by R.J. Bryan and R.L. Norton. Information on this report is available from EPA Emissions Measurement Branch, Research Triangle Park, N.C.

II. VAPOR RECOVERY SYSTEMS

A. VAPOR-BALANCE SYSTEMS

The simplest vapor recovery systems are the vapor-balance systems, which operate on the principle of a simple exchange of materials between the vehicle tank and the service station storage tank. As liquid gasoline is withdrawn from the underground storage tank and pumped into the vehicle tank, it displaces an equivalent volume of vapor-laden air, which either enters the underground tank through a return line to replace the liquid removed or leaks to atmosphere. In principle, with tight connections, such systems might operate indefinitely without loss of hydrocarbons. Achieving such operation is difficult, however, because in practice it is difficult to obtain a tight seal between the nozzle and the fill-neck for all vehicles. Therefore, leakage at this point is frequently encountered. Figure 1 illustrates a typical balance system.

Vapor-balance systems installed by Gulf Oil Corporation and by Standard Oil Company of California at four of the twenty-four systems were the only balance systems in operation in the area during the study period.

Two different piping layouts were used for the vapor balance systems. In the first case vapor return lines were manifolded together and the vapor spaces of the underground tanks were interconnected. In the second design, only the vapor return lines serving the same grade of gasoline were manifolded with no interconnection between tanks.

B. VACUUM-ASSIST SYSTEMS

1. General

In vacuum-assist systems, a negative pressure is maintained within the vapor-return tubing, thus enhancing the capture of vapor at the nozzle-fillneck interface. This approach

Figure 1A. SCHEMATIC DIAGRAM OF
MANIFOLDED BALANCE
SYSTEM






Figure 1B. SCHEMATIC DIAGRAM OF
NON-MANIFOLDED BALANCE
SYSTEM



is usually more effective in capturing vapor at the fillneck, provided sufficient flow of air is maintained, as compared to vapor balance systems.

Air movement, in such systems, is induced by blowers or other aspirating devices (in one of the systems suction is provided by a Venturi ejector operated by compressed air). In all vacuum assisted systems the quantity of vapor-air mixture returned exceeds the amount of gasoline delivered, i.e. the V/L ratio exceeds 1, thus requiring the processing of the excess vapor mixture to capture or destroy the hydrocarbons contained therein. In various systems, this processing is achieved by condensation, by burning with or without a catalyst, or by some combination of these methods. Intermittant accumulation of hydrocarbons by use of vapor holders or activated carbon is sometimes utilized.

Reliability and malfunctioning of the mechanical and electrical components are potential problems associated with vacuum assist systems. Specific problems include: leaks at seals, fittings, and vents; mechanical failure of components; improper sequencing; loss of carbon sorbency; poor combustion conditions in afterburners; and failure to follow operating or maintenance procedures.

Vacuum-assist systems marketed by five manufacturers were investigated in this study. For convenience, in this report, the different designs studied will be identified by the names of the manufacturers. It should be noted that the manufacturer of the vacuum assist systems is not usually responsible for full service installations which include piping, electrical hook-up, P-V valves, nozzles, etc.

Illustrations shown are examples of the vapor recovery systems. The vendors will usually carry a line of varying sized units.

2. Intermark Compression Refrigeration Condensation (CRC) System

A system developed by Intermark Industries, Inc., depends upon compression and refrigeration to condense hydrocarbons from the gas stream. A unique feature is a surge tank for containing the air-hydrocarbon vapor until an appropriate amount for processing is accumulated.

Figure 2 is a schematic diagram of the Intermark Mark I system. Vapors are drawn from the nozzle by a blower; a tee provides for the return of vapor to the underground tank. Vapor laden air passing through the blower bubbles through liquid gasoline in the surge tank. This causes further gasoline evaporation if the air is not initially saturated. Within the tank, a flexible bladder moves a switch, activating the compressor of a refrigeration unit when a predetermined position is reached. Air and vapor are withdrawn from the surge tank, compressed and refrigerated, condensing the hydrocarbons to a liquid which is returned to the surge tank and thence to the storage tank.

Figure 2 also indicates the locations of points (x) which were monitored by the study team to detect possible leakage of hydrocarbon vapors, and the location of a pressure tap (p) which was installed to permit checking the bladder tank pressure at which the compressor was activated. New features since the TRW study were the addition of a vapor flow control valve and use of a different model compressor.

3. Process Products Refrigeration/Adsorption System

A system developed by Process Products, Inc. processes the vapor-laden air, first by condensation, then by adsorption. Figure 3 shows a schematic diagram of this system. Vapor-laden air is collected by means of a blower, located at the pump island, and is delivered to the underground storage




Figure 2. SCHEMATIC DIAGRAM OF INTERMARK SYSTEM (MARK I)




Figure 3. SCHEMATIC DIAGRAM OF PROCESS PRODUCTS SYSTEM

tank. When the pressure in the tank reaches a predetermined value, a second blower is activated, moving air from the tank to a refrigeration unit, from which condensate flows back to the storage tank. As shown in the schematic this model incorporates partial recirculation through the refrigeration unit. The air then passes through carbon beds, which remove much of the remaining hydrocarbons before venting to the atmosphere. When the tank pressure is reduced to another predetermined value, or after thirty minutes, the refrigeration blower is deactivated.

To regenerate the carbon, a pump evacuates the canister (one at a time), delivering the air and desorbed vapors to the air space of the storage tank. This operation is performed automatically, 30 minutes after the refrigeration blower is deactivated.

Figure 3 also indicates the locations of points monitored by the study team to detect possible leakage of hydrocarbon vapors, and the locations of pressure and temperature taps installed to determine tank pressure and condensate temperature. Information provided by the manufacturer indicated that the blower serving the refrigeration unit should be automatically activated when the tank pressure (gauge) reaches one inch of water, and deactivated when tank pressure falls to one half inch.

The condensate temperature is expected to be about 20°F. Modifications to this system since the TRW study consist of the replacement of the belt-driven blower by a direct drive blower and the routing of the refrigerated gas stream directly through the carbon canisters to the atmosphere instead of recycling to the underground tank.

4. Clean Air Engineering Adsorption/Incineration System

A system developed by Clean Air Engineering Inc. employs carbon canisters to adsorb vapors and direct flame burners to dispose of the hydrocarbons released when the sorbent is regenerated. A schematic diagram of the clean air model 5000B is shown in Figure 4. Vapor-laden air is collected by means of a blower and delivered to the processing unit. A tee connector ahead of the blower provides for drainage of any entrained liquid back to the storage tank. A second tee after the blower directs part of the vapor-laden air to the underground tank and the remainder to the processing unit. In the processing unit, activated carbon adsorbs hydrocarbons and the stripped air is vented. After 30 seconds of operation in this mode, a second blower is activated, which draws fresh air through the carbon canisters, delivering the desorbed hydrocarbons to a set of burners, where they are destroyed. Two stages of combustion are employed; the burning continues until the rate of desorption becomes too low to support combustion at either stage, at which time the second blower is deactivated.

Figure 4 also shows the locations of points monitored by the study team to detect possible leakage of hydrocarbon vapors, as well as the location of a pressure tap which was installed to permit checking pressures in the burner manifold. According to the manufacturer, this pressure should normally be maintained at 5 to 5 1/2 inches of water. The modification to this system since the TRW study consists of the replacement of the gasoline engine (which burned the vapors) by a direct-flame, two-stage burner.

5. Environics Adsorption/Catalytic Incineration System

A system developed by Environics, Inc. employs carbon canisters to adsorb vapors and a catalytic reactor to burn the hydrocarbons released when the sorbent is regenerated. A




Figure 4. SCHEMATIC DIAGRAM OF CLEAN AIR ENGINEERING SYSTEM
(Model 5000B)

schematic diagram of the Environics Model A-3000 is shown in Figure 5. Vapor-laden air is collected by means of a blower and delivered to the underground tank and to the processing unit. (Entrained liquid is trapped and drained to the storage tank).

In the processing unit, activated carbon adsorbs hydrocarbons and the stripped air is vented.

At regular intervals of about thirty minutes, one of two carbon canisters is individually flushed with clean air which carries desorbed vapors to the reactor after dilution with additional air, while the other canister is on stream. Cycling is accomplished by a system of solenoid valves.

The reactor is designed to operate at temperatures between 900° and 1200°F. Preheating with an electric element initiates combustion when the unit is activated. When the feed becomes so lean that a temperature of 900°F cannot be maintained, the flushing is terminated. A temperature override switch is also provided, which deactivates the unit in case of overheating; this is set for a limiting temperature of 1300°F.

Figure 5 also shows the locations of points monitored by the study team to detect possible leakage of hydrocarbon vapors, as well as the locations of pressure and temperature taps installed to facilitate observation of the operating parameters of the system. According to information supplied by the manufacturer, a pressure-activated switch allowing the vapor-laden air to enter the carbon canisters should open when the pressure reaches 3 1/2 inches of water. The modifications to this system since the TRW study consist of: 1) the addition of a vapor flow control valve, 2) the rerouting of most of the vapors to the underground tank, and 3) the addition of a thermal overload switch to the reactor.




Figure 5. SCHEMATIC DIAGRAM OF ENVIRONICS SYSTEM (MODEL A-3000)

6. The Hirt System

A system developed by Hirt Combustion Engineers employs an air-actuated ejector to maintain negative pressure in the underground storage tank and burners to destroy the hydrocarbons which are carried through the system. A schematic diagram is shown in Figure 6.

Flow of compressed air is initiated whenever the absolute pressure (for clarity of discussion, performance in terms of absolute pressures is used; in practice, differential pressure actuators are used) in the tank rises above a pre-determined absolute value. The air flows to a set of burners, entraining vapor-laden air from the tank. Combustion is initiated by a pilot light, fueled by propane; an alarm system notifies the station operator in case the pilot flame should fail. The compressed air flow is automatically halted when the absolute pressure in the underground tank falls below a preset value.

Figure 6 also shows the locations of points monitored by the study team to detect possible leakage of hydrocarbon vapors, as well as the locations of existing pressure taps which were used to check on pressures in the storage tank and in the compressed air system. In the single system observed in this study, the preset levels were -0.58 inches of water to activate compressed air flow, and -0.61 inches to deactivate it. This system was designed and built since the TRW study.




Figure 6. SCHEMATIC DIAGRAM OF HIRT SYSTEM

III. METHODS AND EQUIPMENT

A. THE STUDY PLAN

The basic study plan was to undertake repeated inspection of the operational status of vapor-recovery systems and components at a selected group of gasoline filling stations, to identify reliability problems and to monitor parameters which affect vapor control at these stations. Using a combustible gas indicator the frequency and approximate magnitude of vapor losses were to be checked at delivery nozzles during vehicle service and at potential leakage points associated with the various recovery systems. As discussed below, there were several criteria used for inclusion of stations in the study, which included selection from a list of stations which had permits to operate as supplied by San Diego County.

Inspection procedures were developed taking into account the configuration of the vapor recovery system and were designed for one visit per station per week. These visits were performed on varying days and at varying times during the day (inspection visits made only during daylight hours).

B. STATION SELECTION

Information necessary for selecting the stations to be studied, as well as for designing inspection forms, checklists and other program elements, was obtained at meetings and interviews with representatives of the vapor recovery system manufacturing companies, the San Diego County Air Pollution Control District, the U.S. Environmental Protection Agency, and others. The original selection plan called for five stations for each of the manufacturers or types of control systems represented in the general study protocol. These stations were to have throughputs of at least 30,000 gallons per month. In order to have sufficient repeat visits, not all operating

systems of some manufacturers were included. For other manufacturers where the available number of stations was small, some units which were expected to be in operation soon were included. It was not possible to meet the 30,000 gallons/month minimum criteria in all cases, but most of those which had lower monthly throughputs, did dispense high volumes at certain times of day, associated with shift changes. These stations were non-commercial, self-service stations operated by government agencies or local enterprises with large vehicle fleet operations, such as Stations 16 and 21, of the California Highway Patrol; Station 15, the U.S. Postal Service; and Station 3, for Terminix Pest Control. Station 22 was included because it was the only available example of the Hirt Combustion Engineers vapor control system. Table 1 lists the stations selected, the type of control system used, and other pertinent information.

As shown in Table I, monthly throughput observed during the study ranged from 4,600 to 212,500 gallons but most of the stations ranged between 15,000 and 90,000. The number of vapor-control units representing each type of system was either 4 or 5, except for the single Hirt system installation.

C. INSPECTION FORMS

Using information obtained in the preliminary meetings and interviews, the study team developed an inspection strategy for each type of control system, involving determination of the operational status of the unit, observation of the operational sequence, and tests for hydrocarbon leakage at various appropriate points. For each type of system, an inspection form was designed for recording information to be acquired on each inspection visit. These forms are exhibited in Appendix A; they served as a check list of inspection points, as well as a field record.

Table 1. FILLING STATIONS SELECTED FOR STUDY*

| <u>Station No.</u> | <u>Control System</u> | <u>Supplier</u> | <u>No. of Pumps</u> | <u>Throughput, Gallons/mo.</u> | <u>Locality</u> |
|--------------------|-----------------------|------------------|---------------------|--------------------------------|--|
| 1 | Process Products | Standard | 9 | 44,700 | Clairmont, and Clairmont Mesa, San Diego |
| 2 | Clean Air Eng. | R.H. Dairy | 4 | 20,500 | Mt. Ada Road, San Diego |
| 3 | Environics | Terminix | 2 | 4,600 | Vickers and Mercury, San Diego |
| 4 | Clean Air Eng. | Standard | 6 | 87,100 | Tierrasanta Blvd. San Diego |
| 5 | Process Products | Union | 8 | 25,100 | Waring Rd., San Diego |
| 6 | Vapor-balance | Standard | 10 | 44,600 | Baltimore and Lake Murray, La Mesa |
| 7 | Environics | Texaco | 8 | 36,400 | Baltimore and Fletcher Parkway, La Mesa |
| 8 | Intermark | Sears | 8 | 72,900 | Johnson and Fletcher Parkway, El Cajon |
| 9 | Process Products | Standard | 12 | 52,400 | Johnson Ave., El Cajon |
| 10 | Process Products | Mobil | 8 | 60,900 | University and College, San Diego |
| 11 | Intermark | Gemco | 16 | 212,500 | 30th and Highland, National City |
| 12 | Vapor-balance | Gulf | 6 | 39,000 | University and 40th, San Diego |
| 13 | Vapor-balance | Gulf | 6 | 53,000 | University and Boundary, San Diego |
| 14 | Vapor-balance | Gulf | 13 | 63,800 | Texas and El Cajon, San Diego |
| 15 | Environics | Post Office | 2 | 19,200 | Midway Drive, San Diego |
| 16 | Clean Air Eng. | Highway Patrol | 2 | 36,100 | Pacific Highway, San Diego |
| 17 | Clean Air Eng. | Dep't. of Educ'n | | n.a. | Linda Vista Rd., San Diego |
| 18 | Process Products | Standard | 10 | 36,000 | Friars and Frazee, San Diego |
| 19 | Intermark | Standard | 12 | 153,200 | Carmel Valley Rd., San Diego |
| 20 | Intermark | Union | 10 | 63,500 | Santa Fe Dr., Encinitas |
| 21 | Clean Air Eng. | Highway Patrol | 2 | 16,300 | Oceanside Blvd., Oceanside |
| 22 | Hirt | Phillips | 6 | 12,500 | Mission and Canyon, Oceanside |
| 23 | Environics | Phillips | 6 | 68,300 | Elm and Harding, Carlsbad |
| 24 | Environics | Union | 12 | 80,000 | 6th and Robinson, San Diego |

*Not all the stations had completed installations when the study started, but completion was expected soon. The systems at Stations 10 and 19 were not completed during the study. Station 17 was dropped when it became apparent that the monthly throughput was substantially less than had been expected,

D. INSPECTION PROCEDURE

On each inspection visit, the study team announced their presence to the station manager and inquired about the operational status and recent experience with the control system. If the unit was operational, an operation sequence check was performed, and relevant pressures and temperatures were measured and recorded. Serial numbers of component machinery (blowers, compressors, pumps, refrigeration units) were recorded and any replacements noted. Combustible vapor readings were taken at all prescribed locations. In most cases, a number of vehicle tank fillings were monitored for hydrocarbon vapor losses, using a combustible gas meter. The probe tip was moved in a circular motion around the nozzle-filler tube interface at a distance of one half inch. Information on the station's throughput of gasoline was recorded, and the operator's comments solicited, before terminating the inspection.

E. EVALUATING OPERATIONAL STATUS

On each visit to each station, the study team was required to determine whether the vapor control system was operating in accord with design specifications. This was done by observing the performance of the various elements of the system to answer the questions listed under "Operational Sequence Check" on the corresponding inspection form (Appendix A).

For each of the vacuum-assist systems, pressures within the system were measured at strategically located pressure taps as indicated in the schematic diagrams, Figures 2 to 6. Magnehelic gauges having a sensitivity of 0.01 inch of water were used, with self-sealing, quick-connecting Imperial Eastman fittings. With two of the systems, temperatures were also determined. For this purpose thermocouples were used, and the potentials generated were measured with a portable potentiometer (Thermo-Electric Co., Model 31101, "Minimite").

F. DETECTION OF HYDROCARBON VAPOR LEAKAGE

An important aspect of the inspections was the detection of leaks. For this purpose the study team used a Combustible Gas Analyzer, Model SSP, manufactured by Bacharach Instrument Co., with scales reading from 0 to 1000 ppm and from 0 to 1.0 relative to the lower explosive limit (L.E.L.). Readings were taken at the points indicated in Figure 1 through 6 on each visit to each station, and at the fillneck of the vehicle tank for each of the several cars served by the station on each visit.

For studying the effectiveness of the carbon adsorption systems (in removing hydrocarbons from the exhaust air), hydrocarbon detectors were installed at two stations for each of the three vapor-control systems (Process Products, Clean Air Engineering, Environics) which incorporate adsorption. These devices were of two designs. The first, or "latching" type triggers a timer whenever the hydrocarbon concentration exceeds the set point, 1.2 percent or 12,000 ppm, V/V. The second, or "non-latching" type similarly triggers a timer at the set-point but, unlike the first, the timer is stopped whenever the hydrocarbon concentration subsequently falls below the set-point. The timers were checked, readings recorded, and instruments re-set if necessary at each inspection of the six selected stations.

There were several purposes for installation of the hydrocarbon detectors: 1) to indicate whether any hydrocarbon leakage above the set point occurred during normal operation, 2) to indicate whether the carbon beds saturate before regeneration, and 3) to indicate whether high molecular weight hydrocarbons build up on the carbon beds and reduce capacity.

G. PERFORMANCE EVALUATION

For purposes of performance evaluation, effectiveness of vapor collection at the vehicle fuel tank was considered separately from performance of the vapor recovery system itself. That is, it would be possible for a system to be nearly completely effective in vapor collection and yet perform poorly in processing these vapors so as to prevent their discharge to atmosphere. For purposes of evaluating reliability of the processing equipment the term malfunction is defined to include both demonstrable malfunction of a component or evidence of a hydrocarbon loss exceeding 100 ppm (the minimum detectable concentration) using a combustible gas analyzer.

IV. RESULTS AND DISCUSSION

A. GENERAL

During the study, 140 inspection visits were made to the stations listed in Table I, and 506 vehicle fillings monitored. The data on vehicle fillings are shown in Appendix B. In the great majority (88 percent) of visits to vacuum assist stations, some malfunction was detected; in only 14 of 115 visits were the vacuum assist systems found to be operating in accord with the manufacturer's specifications and free from hydrocarbon vapor losses. If the stations which did not operate during the entire study period are excluded, malfunctions were detected in 84 percent of the visits (14 of 89 visits).

Since the magnitude of the losses could not be determined, the results of the study are here presented and discussed in terms of frequency of occurrence of combustible vapor readings relative to certain benchmarks, namely, 100 ppm hydrocarbon (lower scale of the indicator); 0.1 LEL (one tenth of the lower explosive limit, as shown on the upper scale of the indicator); and 0.6 LEL. The 0.1 LEL criterion is based upon an EPA finding which stated when there were no leaks at the nozzle/fillneck interface, hydrocarbon concentrations did not exceed 0.1 LEL. The 0.6 LEL criterion is the upper limit allowed by the San Diego County Air Pollution Control District.

Table II shows for each type of control system, the frequency of inspection, the number and percent of the visits on which the control system was found to be operating correctly and without leaks, the number of vehicle fillings observed and the number and percent of vehicle fillings in which hydrocarbon vapors were not detectable. The four vapor-balance systems, having far fewer mechanical components, evidenced no equipment failures, and since no potential leakage points were accessible for testing, no instances of faulty operation were observed. However, the vacuum-assist systems, when operating correctly, were much more effective in controlling vapor losses at the nozzle.

Table II. SUMMARY OF INSPECTIONS

| Control System | in Study | No. of Visits | Correct Operations ^a | | Vehicle Refuelings | | |
|--------------------|--------------------|---------------|---------------------------------|------------------|---------------------------------------|-------------------------------------|--------|
| | | | No. | % | No. of of Obs. Vehicle Fillings | No. with No HC loss ^b | % |
| Vapor-balance | 4 | 25 | 25 | 100 ^c | 105 | 21 | 20 |
| Intermark | 4 (3) ^e | 25 (19) | 0 | 0 | 85 (70) | 46 | 54(66) |
| Process Products | 5 (2) | 35 (15) | 4 | 11 (27) | 120 (57) | 67 (49) | 56(86) |
| Clean Air Eng. | 4 | 26 | 3 | 12 | 104 | 77 | 74 |
| Environics | 5 | 23 | 1 | 4 | 78 | 24 | 31 |
| Hirt | 1 | 6 | 6 | 100 ^d | 14 | 10 | 71 |
| All Vacuum Systems | 19 (15) | 115 (89) | 14 | 12 (16) | 401 (323) | 224(206) | 56(64) |
| All Systems | 23 (19) | 140 (114) | 39 | 28 (34) | 506(468) | 245(227) | 48(53) |

- a: For this tabulation "Correct Operations" indicates that the operational sequence followed the manufacturer's specifications and that no combustible vapors (hydrocarbon losses) could be detected at preselected check points.
- b. This column indicates the number of fillings observed in which hydrocarbon losses could not be detected; that is, the combustible gas analyzer registered no vapor concentration above its lower detectable limits (100 ppm)
- c. At the stations with vapor-balance systems, operated by Gulf Oil Corporation, clear plastic tubing was installed in the vapor return lines at the beginning of the study. These were intended to permit visual inspection of the lines for possible blockage by accumulated liquid gasoline. After about three weeks this tubing was replaced by ordinary opaque tubing, when it was found that the clear plastic deteriorated rapidly and was easily kinked, causing unsatisfactory operations of the system. It should be noted that when the clear plastic tubing was installed, vapors could be seen to easily bubble through any liquid blockage that did occur.
- d. Although the Hirt system was always operational, the observed frequency of cycling- about once per minute - suggests that air leaks into the system may have been triggering operation more often than satisfactory vapor loss control would require.
- e. Numbers in parentheses denote totals if stations not operating during the study period awaiting retrofit are excluded.

Total system efficiency is not a direct function of nozzle losses as the excess air/vapor ingested and the vapor processing unit efficiency must also be considered.

B. SYSTEM MALFUNCTIONS

During the 115 inspection visits to stations with vacuum assist systems, 174 instances of specific malfunctions were observed, as listed in Table III. The only evidence of malfunction was, in 130 instances, observation of hydrocarbon losses at one of the testing locations specified on the inspection forms. Such malfunctions did not necessarily interfere with the continued operation of the system, but did impair the effectiveness of vapor control. In 36 instances, the systems were inoperable or were, for other reasons, not in operation at the time of the inspection visit. The distribution of these 36 malfunctions is shown in Table IV. In only 9 of these instances (8 percent of the visits) were equipment failures the immediate cause of the shutdown. Another 15 instances were due to failure of station personnel to activate either the vapor collection device or the entire system. In the remaining instances, disconnected vacuum hoses were responsible 8 times, and automatic shutdown due to overheating of a catalyst reactor occurred 4 times. Thus, although the control equipment was out of operation on approximately one third of all the inspection visits, only one third of these instances (13, or 11 percent of the visits) were attributable to system failures. In another 8 instances, the systems were operable but an indication of a malfunction was described by the station operator (4 instances of excessive cycling resulting in extremely high electric bills, 4 instances of poor ITT valve adjustment).

On 14 other inspection visits the systems were inoperable due to the fact that equipment installation had not been completed. Of these visits, 7 occurred at one station where the processing unit had been disconnected because of a fire and not reconnected. The

Table III. FREQUENCY OF OCCURRENCE OF SPECIFIC MALFUNCTIONS
AT VACUUM ASSIST STATIONS

| | |
|--|----------|
| Hydrocarbons observed at blowers and pumps | 33 |
| Hydrocarbons observed at underground tank vent | 25 |
| Hydrocarbons observed during burner ignition | 19 |
| Hydrocarbons observed at surge tank vent | 13 |
| Hydrocarbons observed at carbon canister vent | 9 |
| Unit turned off | 8 |
| Vacuum hoses disconnected | 8 |
| Hydrocarbons observed at reactor vent | 7 |
| Hydrocarbons observed at condenser relief vent | 7 |
| Island blower not on | 7 |
| Hydrocarbons observed at piping connection | 6 |
| Hydrocarbons observed at compressor | 6 |
| Hydrocarbons observed at compressor relief vents | 5 |
| Poor ITT valve adjustment | 4 |
| Unit off due to temperature override | 4 |
| Broken blower belt | 4 |
| Constant cycling by unit controls | 4 |
| Blower motor failure | 3 |
| Unit down due to compressor failure | <u>2</u> |
| Total | 174 |

Table IV. FREQUENCY OF CAUSES OF FAILURE TO OPERATE
AT VACUUM ASSIST SYSTEMS

| | | |
|----|------------------------------------|----------|
| 1. | Unit turned off | 8 |
| 2. | Vacuum hoses disconnected | 8 |
| 3. | Vapor-collection blower turned off | 7 |
| 4. | Broken blower belt | 4 |
| 5. | Automatic temperature cutoff | 4 |
| 6. | Blower motor failure | 3 |
| 7. | Compressor failure | <u>2</u> |
| | Total | 36 |

other 7 instances were noted at another station where installation of a new compressor had not been completed. Table V lists the observed malfunctions by manufacturer.

Hydrocarbon losses, evidenced by testing with the combustible gas analyzer, were predominantly associated with, or caused by equipment failure, as shown in Table VI. Approximately two thirds of the observations appeared to be attributable to such failures. The cause of hydrocarbon observations at the underground tank vent could be attributed to bulk drops in only 10 percent of these occurrences. Other causes were incomplete or faulty installation, as well as improper adjustment or failure to use the equipment properly. About twenty percent of the hydrocarbon loss observations occurred during normal system operation. These included small losses at the Clean Air Engineering burners prior to ignition, and at the reactor vent of the Environics system. Such losses ordinarily do not continue for any protracted period.

C. MEASURED OPERATIONAL PARAMETERS

Pressures and temperatures recorded at the taps described, for the various vacuum-assist vapor control systems, were compared with the values specified as standard by the manufacturers, as given in Section II. Notes reflecting the observations on these parameters are presented in Appendix C.

For the Intermark System, no pressures or temperatures in the CRC unit or bladder tank were specified. Pressures as high as 7.5 inches of water in the surge tank were observed when the bladder was fully distended. When the level indicator registered about one eighth of capacity, observed pressure ranged from about 0.5" to 2.0".

With the Process Products systems, only two of the stations provided useful data; the other units were inoperative most of the time, awaiting delivery of vapor collection blowers. The two operating

Table V. FREQUENCY OF OCCURRENCE OF SPECIFIC
MALFUNCTION BY MANUFACTURER

ENVIRONICS - 23 visits

| | |
|--------------------------------------|----------|
| HC at Reactor vent - | 7 |
| HC at Carbon Canister Vent - | 6 |
| HC at Underground Tank Vent - | 6 |
| HC at Blowers and Pumps - | 6 |
| Unit Off Due To Temperature Override | 4 |
| Poor ITT Valve Adjustment - | 4 |
| Blower Motor Failure - | 3 |
| HC at Unit Piping - | 2 |
| Vacuum Lines Disconnected - | 2 |
| Unit Turned Off - | <u>1</u> |
| | 41 |

PROCESS PRODUCTS - 35 visits

| | |
|-------------------------------|----------|
| HC at Underground Tank Vent - | 15 |
| HC at Blowers and Pumps - | 14 |
| Island Blower Not on - | 7 |
| Processing Unit Not on - | 6 |
| Excessive Cycling - | 4 |
| HC at Carbon Canister Vent - | 3 |
| HC at Unit Piping - | <u>1</u> |
| | 50 |

PROCESS PRODUCTS (St #5 and St #18 only) - 15 visits

| | |
|-------------------------------|----------|
| HC at Underground Tank Vent - | 5 |
| HC at Blowers and Pumps - | 4 |
| HC at Carbon Cannister Vent - | 3 |
| Excessive Cycling - | <u>3</u> |
| | 15 |

Table V. FREQUENCY OF OCCURRENCE OF SPECIAL
MALFUNCTION BY MANUFACTURER (continued)

INTERMARK - 25 visits

| | |
|--------------------------------|----------|
| HC at Surge Tank Vent - | 13 |
| HC at Blowers and Pumps - | 8 |
| HC at Condenser Relief Vent - | 7 |
| HC at Compressor - | 6 |
| Vacuum Lines Disconnected - | 6 |
| HC at Compressor Relief Vent - | 5 |
| Broken Blower Belt - | 4 |
| HC at Unit Piping | 3 |
| HC at Underground Tank Vent - | 2 |
| Compressor Failure - | <u>2</u> |
| | 56 |

CLEAN AIR - 26 visits

| | |
|--------------------------------------|----------|
| HC at Burner Exhaust During Ignition | 19 |
| HC at Blowers and Pumps - | 5 |
| HC at Underground Tank Vent - | 2 |
| Unit Off - | <u>1</u> |
| | 27 |

HIRT - 6 visits

Unit prone to vacuum leaks which cause unit to
fire approximately every minute.

Table VI. FREQUENCY OF CAUSES OF HYDROCARBON LOSSES
AT VACUUM ASSIST STATIONS

| | <u>Number Observed</u> | <u>Per Cent of Total</u> |
|---|------------------------|------------------------------|
| Malfunctions due to equipment failure | 52 | 37.7 |
| Malfunctions as consequence of equipment failures* | 46 | 33.3 |
| Malfunctions inherent to systems (i.e., hydrocarbons observed at burner ignition are usually very small and last for less than 30 seconds). | 26 | 18.8 |
| Malfunctions due to poor installation | 6 | 4.4 |
| Malfunction due to improper unit adjustment | 8 | 5.8 |
| Total | <u>138</u> | <u>100.0</u> |

* Example:

Failure of equipment may cause underground tank pressure to increase if blowers are operating but no processing is taking place. This will force venting and hydrocarbons will be detected at the underground vent.

units had slightly different settings, but pressures showed consistent behavior from week to week. At Station 5, the refrigeration unit was found to start at pressures ranging from 3.5 to 4.5" and to stop at pressures ranging from 0.2 to 1.0" H₂O. At Station 18, the unit started at 1.0 to 1.1" and stopped at 0.3 to 0.5" H₂O. (Manufacturer's information suggested start and stop pressures of 1" and 0.5" H₂O, respectively). The condensate temperature was measured only at Station 18 and was found to vary from 12 to 40°F (expected was about 20°F).

For the Clean Air Engineering systems, design pressure at the burner manifold was 5 to 5 1/2" w.c. Stations 16 and 21 operated consistently within this range. Station 2, for unknown reasons, operated at pressures ranging from 4" to 15", while Station 4 operated in the range of 3.2" to 3.5". The burner system at the latter station had reportedly been readjusted and the manifold pressure reduced in an attempt to control accumulation of soot in the burner.

In the Environics System, the pressure-actuated switch was expected to open at 3.5" H₂O w.c. In actual operation, the switches opened at lower pressures; 2.6" in one case, 1.6" in another. Reactor temperatures also were sometimes found outside the range (900-1200°F), expected for the automatic controls. In one case the reactor pump started when the reactor was at a temperature of 1290°F and continued running until the reactor temperature dropped to 740°F. In another, the reactor was at 848°F when the pump started, and at 760°F when the pump stopped.

In the single Hirt system installation (Station 22), the small burner and the compressed air flow were usually, but not always, activated at -0.58" H₂O; on one visit, the observed activation pressure was -0.61". The burner system was deactivated at -0.61" to -0.65". The controls for these pressures are accessible to station personnel and may occasionally have been adjusted by them.

With respect to the vacuum-assist systems as a group, it appears that the operating parameters are not consistently maintained within design limits; however, the extent to which this lack of control may adversely affect vapor control cannot be assessed from the data obtained in this study.

D. HYDROCARBON LOSSES ON FILLING VEHICLE TANKS

As indicated in Table II, no leaks were detected at the nozzle-fillneck interface in about half of the observed vehicle fillings. The actual fraction was 20 percent with vapor-balance systems, and from 31 to 74 percent with the various vacuum-assist systems, averaging 56 percent for all vacuum-assist units.

A higher proportion of no leak fills is evident if attention is directed only to occasions when the study team found on checking, that the vapor collection blower was operating. Also deleted in this consideration are the stations where the operators complained of poor vapor collection due to poor ITT valve adjustment. About one fourth of the fillings are excluded by this condition. Among those that remain, the proportion of successful control was from 71 to 89 percent with the various vacuum-assist systems, averaging 79 percent.

The proportion of successful control will, naturally be higher, also, if "successful" is defined more leniently. Although the combustible gas analyzer could not be used for a quantitative determination of vapor losses, it seems likely, on the whole, that when higher vapor concentrations are detected, they correspond to greater vapor losses. Also it is possible that vapor losses at times might be negligible, even though detectable with the analyzer.

Accordingly, Table VII lists the results of the refueling checks where hydrocarbon concentrations at the nozzle-fillneck interface were less than three different criterion levels. These were 100 ppm, 0.1 LEL, and 0.6 LEL, respectively. (For gasoline vapors,

Table VII. FREQUENCIES OF OBSERVED CONCENTRATIONS OF HYDROCARBONS AT NOZZLE-FILLNECK INTERFACE AT SELECTED VEHICLE FILLINGS*

| MANUFACTURER | Number of Fillings * | Frequency below given level | | | | | |
|--------------------|----------------------|-----------------------------|---------|-----------------------|---------|-----------------------|---------|
| | | ≤100 ppm | | ≤0.1 LEL ^a | | ≤0.6 LEL ^a | |
| | | No. | Percent | No. | Percent | No. | Percent |
| Vapor Balance | 105 | 21 | 20 | 40 | 38.1 | 43 | 41.0 |
| Intermark | 52 | 46 | 88.5 | 49 | 94.2 | 49 | 94.2 |
| Process Products | 57 | 49 | 86.0 | 51 | 89.5 | 51 | 89.5 |
| Clean Air | 104 | 76 | 73.1 | 86 | 82.7 | 89 | 85.6 |
| Environics | 28 | 20 | 71.4 | 23 | 82.1 | 23 | 82.1 |
| Hirt | 14 | 10 | 71.4 | 13 | 92.9 | 13 | 92.9 |
| All Vacuum Systems | 255 | 201 | 78.8 | 222 | 87.1 | 225 | 88.2 |
| All Systems | 360 | 222 | 61.7 | 262 | 72.7 | 268 | 74.4 |

* Fillings when vapor collection system of nozzle was operating correctly

a. LEL: Lower explosive limit

the lower explosive limit is approximately 1.2 percent by volume, or 12,000 ppm, V/V.) These figures refer only to those fillings in which the vapor collection system, at the nozzle, was operating as stated above. They show that, of 268 cases with concentrations below 0.6 LEL, 262 or only six less, were also below 0.1 LEL. The number of cases with concentrations below 100 ppm, however, dropped to 222.

Judged at the 0.1 LEL criterion level, as Table VII shows, the vapor-balance systems are far less effective than vacuum-assist systems in capturing vapors during the filling of vehicle tanks. Thirty-eight percent of the fillings with vapor-balance systems were below this level while the corresponding proportion for various vacuum-assist systems, when operating properly, was from 82 to 94 percent.

E. EFFECTIVENESS OF SYSTEMS WHEN OPERATING OPTIMALLY

Since both system malfunctions and operator inattention can prevent vapor-control systems from operating at full efficiency, it is of interest to examine the study data to determine what degree of effectiveness can be observed at those stations where these problems were least apparent. Table VIII shows, for each type of system, the record of successful capture of vapors at the nozzle using three different criterion levels, for the single station having the best record.

With the vapor-balance system, the best record of capture at the 0.6 LEL criterion level was slightly over 50 percent. With vacuum-assist systems, however, four of the five systems demonstrated better than 95 percent success in limiting nozzle losses to the 0.6 LEL criterion level.

Table VIII. DEGREE OF CONTROL ACHIEVED WITH VAPOR-CONTROL STATIONS
OPERATING OPTIMALLY

| <u>System</u> | <u>Station^a</u> <u>I.D. No.</u> | <u>No. of</u> <u>Fillings Observed</u> | <u>Tests showing less than</u> | | | | | |
|------------------|---|---|--------------------------------|----|----------------|-----|----------------|-----|
| | | | <u>100 ppm</u> | | <u>0.1 LEL</u> | | <u>0.6 LEL</u> | |
| | | | No. | % | No. | % | No. | % |
| Vapor-balance | 6 | 29 | 10 | 34 | 13 | 45 | 15 | 52 |
| Intermark | 11 | 37 | 34 | 92 | 35 | 95 | 36 | 97 |
| Process Products | 5 | 24 | 23 | 96 | 23 | 96 | 23 | 96 |
| Clean Air Eng. | 21 | 19 | 18 | 95 | 19 | 100 | 19 | 100 |
| Environics | 3 | 8 | 5 | 63 | 6 | 75 | 6 | 75 |
| Hirt | 22 | 14 | 10 | 70 | 11 | 77 | 14 | 100 |

a. Station showing the highest proportion of reliable operation (fewest malfunctions or hydrocarbon leaks) during the study period.

F. EFFECT OF NOZZLE TYPE ON VAPOR LOSSES (WITH VAPOR-BALANCE SYSTEMS)

An insight into the possible importance of seemingly minor details of system construction was fortuitously furnished as the result of a system change which occurred during the study. About three weeks after the beginning of the study, many of the original nozzles of the vapor balance systems were replaced by new nozzles. The new design incorporated a metal disc and Teflon seat, a device intended to provide an improved seal between the nozzle and the fillneck while avoiding undue stress on the rubber boot sheathing the nozzle. Both were manufactured by the same firm.

A comparison of the results obtained before and after the change shows clearly that the performance of the new nozzles was inferior to that of the old. The results are shown in Table IX. With the original nozzles, vapor losses were detected in slightly more than half the fillings (55 percent); with the new nozzles, the proportion rose to over 90 percent. With the original nozzles, fewer than one fourth of the losses (23 percent) reached the 0.6 LEL criterion; with the new nozzles, more than three quarters (78 percent) did so.

G. EFFECT OF ATTENDANT SERVICE VS. SELF-SERVICE ON VAPOR LOSSES

Several stations included in the study permitted customers to use the pumps to fill their own vehicle tanks. Table X shows, for each type of vapor control system, a comparison of the vapor loss experience in such stations with the experience where service was performed by attendants; the data used in compiling the table are taken only from those inspection visits on which the vacuum system was operating satisfactorily. For Intermark and Clean Air Engineering control systems, vapor losses were observed in a smaller proportion of fillings at self-service stations than at other stations. For Environics and vapor-balance systems, the reverse was true.

Table IX. FREQUENCIES OF OBSERVED CONCENTRATIONS OF HYDROCARBONS
AT NOZZLE-FILLNECK INTERFACE EXCEEDING VARIOUS CRITERION
VALUES, WITH DIFFERENT NOZZLES (VAPOR-BALANCE SYSTEMS)

| Nozzles ^a | Number of Fillings | Frequency of Exceeding Level | | | | 0.6 LEL ^b | |
|----------------------|-----------------------|------------------------------|---------|----------------------|---------|----------------------|---------|
| | | 100 ppm | | 0.1 LEL ^b | | | |
| | | No. | Percent | No. | Percent | No. | Percent |
| Original | 31 | 17 | 55 | 9 | 29 | 7 | 23 |
| Replacement | 74 | 67 | 91 | 59 | 80 | 58 | 78 |

a. The original nozzles were OPW Model 7VN
the replacements were OPW Model 7YP

b. LEL: Lower explosive limit

Table X. VAPOR LOSSES OBSERVED AT SELF-SERVICE AND ATTENDANT-SERVICE STATIONS

| Control System | Self-Service ^a | | | Attendant-Service | | |
|---------------------------|---------------------------|--------------------|-------------|-----------------------|---------------------------------|-------------|
| | Number of Fillings | Losses Observed | Per Cent | Number of Fillings | Losses ^a Observed | Per Cent |
| Intermark | 37 | 3 | 8 | 15 | 3 | 20 |
| Clean Air Eng. | 48 | 9 | 19 | 56 | 17 | 30 |
| Environics | 9 | 4 | 44 | 19 | 4 | 21 |
| Vacuum-Assist Subtotal | 94 | 16 | 17 | 90 | 24 | 27 |
| Vapor-Balance | 45 | 41 | 91 | 60 | 43 | 72 |
| All | 139 | 57 | 41 | 150 | 67 | 44 |

a. Criterion is detection of hydrocarbons at 100 ppm or above

These differences are not statistically significant and, therefore, furnish no clear evidence that vapor losses at the nozzle are either more or less likely when vehicles are serviced by their drivers than when service-station attendants perform the operation.

H. EFFECT OF VEHICLE FILLNECK CONFIGURATION ON VAPOR LOSSES

In testing the vapor losses on filling vehicle tanks, it was obvious that observed losses were sometimes caused by difficulty of fitting the nozzle to the fillneck, due to unusual and inconvenient configurations of the fillneck or obstructions on the vehicle. Such occurrences were noted on the inspection records.

About forty such observations were recorded, or less than ten percent of the 506 fillings observed. A list of the vehicle models and model-years involved is given in Appendix D, which shows that automobiles of at least eleven manufacturers exhibited poor fits. Only one model (the Chevrolet Corvette) appears more than once in the list. It is therefore apparent that the problem, although a relatively minor one, is likely to be widely encountered.

I. LIQUID LOSSES IN FILLING VEHICLES

A condition known as "spitback" or "spillage", in which liquid gasoline is lost from the tank either after the nozzle is withdrawn from the vehicle fillneck or during filling, was observed by the study team in eight instances, while monitoring more than 500 vehicle fillings. This corresponds to an overall frequency of 1.6 percent. Of these 8 instances, 3 occurred with vapor-balance systems (3 in 105 fillings) and 5 with vacuum-assist systems (5 in 401 fillings).

Some station managers and operators have expressed concern about possible losses of liquid into the vapor line, from which the liquid would drain, unobserved, into the storage tank. The occurrence of spitback may appear to lend substance to these concerns in some cases. However, the study team was unable to detect such liquid losses, and no conclusion can be reached as to whether they occurred during the course of the study.

J. VAPOR LOSSES THROUGH CARBON CANISTERS

Six hydrocarbon detectors were installed at stations with vacuum-assist systems containing carbon canisters. The data are shown in Appendix E. At one station, the detector circuit was tripped shortly after installation, indicating some vapor loss i.e. in excess of 1.2% by volume. After the detector was reset on the next inspection visit, no further losses were detected. However, the vapor control system was not actually in operation during most of the time monitored. At another station, a detector having the accumulating record feature showed a total activation time of 2.6 hours during six weeks of monitoring.

The two observations described occurred at stations equipped with the Environics system. None of the other detectors showed any indications of vapor losses through the carbon canisters.

V. CONCLUSIONS

A. EFFECTIVENESS OF VAPOR RECOVERY SYSTEMS IN CAPTURING HYDROCARBON VAPORS WHEN FILLING VEHICLE TANKS

1. The study demonstrated that several vacuum-assist vapor recovery systems, when operating optimally, can be effective in capturing gasoline vapor losses at the nozzle-fillneck interface. In more than 90 percent of vehicle fillings in large retail gasoline outlets measured hydrocarbon levels near the nozzle were less than 0.6 LEL. In contrast, vapor-balance systems, at best, prevented losses in only about half of the fillings.
2. Under conditions of this study, vacuum-assist vapor recovery systems are found to be non-operational more than vapor-balance systems. When the vacuum-assist stations were not operating, the vapor balance systems were found to be more effective in control of vapors at the nozzle/fillneck interface.
3. Vapor capture is as effective, on the whole, for self-service gasoline marketing as for ordinary attendant-service.
4. The type of delivery nozzle used can have an important effect on vapor capture, especially with vapor-balance systems.
5. A small proportion (less than 10 percent during study) of vehicles served may be expected to have fillneck configurations incompatible with effective use of nozzles in use during this study.

6. In a very small proportion of fillings, liquid losses may be observed as a result of drainage from an overfilled tank ("spitback" or "spillage").

Concern has been expressed about the possibility of liquid returning to the storage tank, unobserved, via the vapor line; the study did not evaluate this problem.

B. OPERATIONAL RELIABILITY OF VAPOR RECOVERY SYSTEMS

1. Reliability of the system in use, as shown by 140 inspection visits, varied from good to poor. Equipment failures caused shutdown of the units in less than ten percent of the inspections, although tardy delivery of components and delays in installation and maintenance resulted in non-operation of the systems in about one third of the inspection visit. (Three systems from Process Products and one from Intermark remained out of operation from this cause throughout the study.)
2. Only a few of the vacuum assist units operated reliably and without vapor leaks throughout the study. One hundred and thirty-eight instances of hydrocarbon losses from leaks in the vapor recovery systems were detected; the predominant cause of these leaks was system failure of some sort.
3. Incorrect operation or inattention by station operators was a factor in about 20 percent of the observed malfunctions.
4. Operating parameters (pressure and temperature) as observed in the inspections were frequently different from those specified by the manufacturers. It is not clear to what extent these deviations may have resulted from, or possibly caused, system malfunctions.

5. Hydrocarbon vapors were detected in the effluent air from carbon adsorption units in two of six systems tested. The significance of such losses has not been evaluated.

APPENDIX A
Inspection Forms

Time In _____

Time Out _____

Date _____

Inspector _____

INSPECTION FORM - VAPOR BALANCE SYSTEMS

Station _____

Address _____

1. Atmospheric Conditions

Temperature _____

Sky Conditions _____

Wind Speed _____

Humidity _____

2. Vehicle Fill Nozzle

Type of Nozzle _____

Make of car being filled _____

Explosimeter reading _____

Operator attempt to make a good fit Yes _____ No _____

3. Vapor Return Line

Vacuum at Nozzle Yes _____ No _____

If No, Explain (if reason is known)

Kinks or Liquid Blockage in lines Yes _____ No _____

Does Operator attempt to straighten

Vehicle Fill Nozzle

_____ Type of nozzle _____
_____ Make of car being filled _____
_____ _____
_____ Explosimeter reading _____
Yes _____ No _____ Operator attempt to make a good fit Yes _____ No _____
_____ Location of gas inlet on car _____

_____ Type of nozzle _____
_____ Make of car being filled _____
_____ _____
_____ Explosimeter reading _____
Yes _____ No _____ Operator attempt to make a good fit Yes _____ No _____
_____ Location of gas inlet on car _____

_____ Type of nozzle _____
_____ Make of car being filled _____
_____ _____
_____ Explosimeter reading _____
Yes _____ No _____ Operator attempt to make a good fit Yes _____ No _____
_____ Location of gas inlet on car _____

Time In _____

Date _____

Time Out _____

Inspector _____

INSPECTION FORM - INTERMARK MARK I

Station _____

Address _____

1. Atmospheric Conditions

Temperature _____

Sky Conditions _____

Wind Speed _____

Humidity _____

2. Vehicle Fill Nozzle

Type of Nozzle _____

Make of car being filled _____

Explosimeter reading _____

Operator attempt to make a good fit Yes _____ No _____

3. Vapor Return Line

Vacuum at Nozzle Yes _____ No _____

If No, Explain (if reason known)

Kinks or Liquid Blockage in Lines Yes _____ No _____

Does Operator attempt to straighten

lines to minimize liquid blockage Yes _____ No _____

4. Tank Vent

Explosimeter reading _____

5. Tank Drop

Tank Drop made during visit Yes _____ No _____

Volume of Tank Drop (if known) _____

6. Vapor Collection Blower

Explosimeter Reading _____

Condition of drive belts Good _____ Poor _____

7. Surge Tank

Explosimeter Reading _____

Bladder Condition Good _____ Poor _____

8. Compressor

Condition Good _____ Poor _____

Explosimeter Reading

- At Compressor _____

- At Compressor Relief Valves _____

9. Condenser Pressure Relief Valve

Explosimeter Reading _____

10. Refrigeration Unit

Condition Good _____ Poor _____

11. Overall Piping

Explosimeter Reading _____

12. Operational Sequence Check

Vapor collection blower starts with

dispensing Yes _____ No _____

Vapor collection blower stops when

dispensing stops Yes _____ No _____

Compressor starts when level switch

in surge tank reaches design level (1/8 capacity) Yes _____ No _____

Compressor stops when bladder level

drops to design shut off level Yes _____ No _____

Refrigeration unit goes through

defrost cycle (20 min.) Yes _____ No _____

13. Comments

Time In _____

Date _____

Time Out _____

Inspector _____

INSPECTION FORM - PROCESS PRODUCTS

Vapor Savor Model No. _____

Station _____

Address _____

1. Atmospheric Conditions

Temperature _____

Sky Conditions _____

Wind Speed _____

Humidity _____

2. Vehicle Fill Nozzle

Type of Nozzle _____

Make of car being filled _____

Explosimeter reading _____

Operator attempt to make a good fit Yes _____ No _____

3. Vapor Return Line

Vacuum at Nozzle Yes _____ No _____

If No, explain (if reason is known)

Kinks or Liquid Blockage in lines Yes _____ No _____

Does Operator attempt to straighten
lines to minimize liquid blockage Yes _____ No _____

4. Tank Vent

Explosimeter reading _____

5. Tank Drop

Tank Drop made during visit Yes _____ No _____

Volume of Tank Drop (if known) _____

6. Island Blower

Explosimeter reading _____

Condition of drive belt Good _____ Poor _____

7. Vapor Refrigeration Blower

Explosimeter reading _____

Condition of drive belt Good _____ Poor _____

8. Carbon Regeneration Blower

Explosimeter reading _____

Condition of drive belt Good _____ Poor _____

9. Carbon Canister Vent

Explosimeter reading _____

10.

11-10. Overall Piping

Explosimeter reading _____

12-11. Operational Sequence Check

Island blower starts with dispensing Yes _____ No _____

Island blower stops when dispensing stops Yes _____ No _____

Refrigeration blower starts when tank
pressure reaches 1" H₂O Yes _____ No _____

Refrigeration blower stops after four
15 min. cycles or when tank pressure
reaches 1/2" H₂O. Yes _____ No _____

Carbon regeneration blower starts when
refrigeration blower stops. Yes _____ No _____

13-12. Comments

Time in _____

Date _____

Time out _____

Inspector _____

INSPECTION FORM - CLEAN AIR ENGINEERING 500B & 1000B

Model No. _____

Station _____

Address _____

1. Atmospheric Conditions

Temperature _____

Sky Conditions _____

Wind Speed _____

Humidity _____

2. Vehicle Fill Nozzle

Type of Nozzle _____

Make of car being filled _____

Explosimeter reading _____

Operator attempt to make a good fit-- Yes _____ No _____

3. Vapor Return Line

Vacuum at Nozzle Yes _____ No _____

If No, Explain (If reason is known)

Kinks or Liquid Blockage in lines Yes _____ No _____

Does Operator attempt to straighten lines

to minimize liquid blockage Yes _____ No _____

4. Tank Vent

Explosimeter reading _____

5. Tank Drop

Tank Drop made during visit Yes _____ No _____

Volume of Tank Drop (if known) _____

6. Vapor Collection Blower

Explosimeter reading _____

Condition of Drive Belt Good _____ Poor _____

7. Carbon Canister Vent

Explosimeter reading _____

8. Burner Exhaust

Explosimeter reading _____

9. Overall Piping

Explosimeter reading _____

10. Operational Sequence Check

Vapor Blower starts with dispensing - Yes _____ No _____

Vapor Blower stops when stage two

burner stops - Yes _____ No _____

Stage two burner starts when stage

one burner stops - Yes _____ No _____

Burner ignition energized when

dispensing stops - Yes _____ No _____

11. Comments

Time in _____

Date _____

Time out _____

Inspector _____

INSPECTION FORM - CLEAN AIR ENGINEERING 2500B & 5000B

Model No. _____

Station _____

Address _____

1. Atmospheric Conditions

Temperature _____

Sky Conditions _____

Wind Speed _____

Humidity _____

2. Vehicle Fill Nozzle

Type of Nozzle _____

Make of car being filled _____

Explosimeter reading _____

Operator attempt to make a good fit Yes _____ No _____

3. Vapor Return Line

Vacuum at Nozzle Yes _____ No _____

If No, Explain (if reason is known)

Kinks or liquid blockage in lines Yes _____ No _____

Does Operator attempt to straighten

lines to minimize liquid blockage Yes _____ No _____

4. Tank Vent

Explosimeter reading _____

5. Tank Drop

Tank Drop made during visit Yes _____ No _____

Volume of Tank Drop (if known) _____

6. Vapor Collection Blower

Explosimeter reading _____

Condition of drive belts Good _____ Poor _____

7. Carbon Canister Vent

Explosimeter reading _____

8. Burner Pump

Explosimeter reading _____

Condition of drive belt _____

9. Burner Exhaust

Explosimeter reading _____

10. Overall Piping

Explosimeter reading _____

11. Operational Sequence Check

- Vapor collection blower starts with dispensing - Yes _____ No _____
- Burner pumps start with dispensing Yes _____ No _____
- Burner ignition energized when burner pump starts - Yes _____ No _____
- If neither burner starts, burner pump stops - Yes _____ No _____
- Once burner pump stops, does not start until dispensing starts - Yes _____ No _____
- Second stage burner starts when first stage burner stops - Yes _____ No _____
- Burner pump stops when second stage burner stops - Yes _____ No _____
- Vapor collection blower stops when dispensing stops - Yes _____ No _____

12. Comments

Time In _____

Date _____

Time Out _____

Inspector _____

INSPECTION FORM - ENVIRONICS VAPOX A-3000, A-1500, A-400 & A-400-M

Model No. _____

Station _____

Address _____

1. Atmospheric Conditions

Temperature _____

Sky Conditions _____

Wind Speed _____

Humidity _____

2. Vehicle Fill Nozzle

Type of Nozzle _____

Make of car being filled _____

Explosimeter reading _____

Operator attempt to make a good fit Yes _____ No _____

3. Vapor Return Line

Vacuum at Nozzle Yes _____ No _____

If No, explain (if reason is known)

Kinks or Liquid Blockage in lines Yes _____ No _____

Does Operator attempt to straighten
lines to minimize liquid blockage Yes _____ No _____

4. Tank Vent

Explosimeter reading _____

5. Vapor Collection Blower

Explosimeter reading _____

Condition of drive belt Good _____ Poor _____

6. Carbon Canister Vent

Explosimeter reading _____

7. Reactor Vent

Explosimeter reading _____

Reactor down due to 1300°F override

during visit Yes _____ No _____

8. Carbon Regeneration Blower

Explosimeter reading _____

Condition of drive belt Good _____ Poor _____

9. Overall Piping

Explosimeter reading _____

10. Operational Sequence Check

Vapox A-3000

Vapor Collection Pump starts with dispensing Yes _____ No _____

Pressure switch opens at 3.5" H₂O Yes _____ No _____

Vapor collection pump stops when dispensing stops- Yes _____ No _____

Carbon regeneration pump stops when reactor temperature is below 900°F or above 1300°F. Yes _____ No _____

Vapox A-1500, A-400 & A-400-M

Vapor collection blower starts with dispensing Yes _____ No _____

Pressure switch opens at 3.5" H₂O Yes _____ NO _____

Vapor collection blower stops when dispensing is over- Yes _____ No _____

Carbon regeneration blower starts when dispensing is over- Yes _____ No _____

Carbon regeneration blower stops when dispensing starts- Yes _____ No _____

Carbon regeneration stops when reactor temperature is below 900°F or above 1300°F Yes _____ No _____

11. Tank Drop

Tank Drop made during visit

Yes _____ No _____

Volume of Tank Drop (if known) _____

12. Comments

Time In _____

Date _____

Time Out _____

Inspector _____

INSPECTION FORM - HIRT/HAZELETT

Station _____

Address _____

1. Atmospheric Conditions

Temperature _____

Sky Conditions _____

Wind Speed _____

Humidity _____

2. Vehicle Fill Nozzle

Type of Nozzle _____

Make of car being filled _____

Explosimeter reading _____

Operator attempt to make a good fit Yes _____ No _____

3. Vapor Return Line

Vacuum at Nozzle Yes _____ No _____

If No, Explain (if reason is known)

Kinks or Liquid Blockage in lines Yes _____ No _____

Does Operator attempt to straighten

lines to minimize liquid blockage

Yes _____ No _____

4. Tank Vent

Explosimeter reading _____

5. Tank Drop

Tank Drop made during visit

Yes _____ No _____

Volume of Tank Drop (if known) _____

6. Burner Exhaust

Explosimeter reading _____

Pilot operating during visit

Yes _____ No _____

7. Propane Gas Supply

Satisfactory _____

Unsatisfactory _____

8. Compressed Air Supply

Satisfactory _____

Unsatisfactory _____

9. Overall Piping

Explosimeter reading _____

10. Operational Sequence Check

Compressed Air starts when tank pressure
reaches $-0.15'' \text{ H}_2\text{O}$

Yes _____ No _____

Small burner comes on when tank
pressure reaches $-0.15'' \text{ H}_2\text{O}$

Yes _____ No _____

Large burner comes on when tank
pressure reaches $+0.1'' \text{ H}_2\text{O}$

Yes _____ No _____

Compressed air stops when tank
pressure reaches $-0.23'' \text{ H}_2\text{O}$ (for
small burner)

Yes _____ No _____

Compressed air stops when tank pressure
reaches $-0.5'' \text{ H}_2\text{O}$ (for large burner)

Yes _____ No _____

11. Comments

APPENDIX B

Automobiles Tested

AUTOMOBILES TESTED

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|-------------|--------------|-------------|--|-------------------------------|---------------------------|---------------------|
| Oldsmobile | - | 1973 | 1 | - | 1.0 + LEL | - |
| Ford | Fairlane | 1969 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Ford | Pinto | 1972 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Nova | 1970 | 1 | Under License Plate | 1.0 + LEL | Unit down |
| Mercury | - | 1968 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Ford | Maverick | 1970 | 1 | Rear Panel | 800 PPM | Unit down |
| Datsun | - | 1975 | 1 | Right Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Pickup | 1972 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Dodge | Polara | 1967 | 1 | Under License Plate | 1.0 + LEL | Poor Fit Unit down |
| Buick | Skylark | 1964 | 1 | Under License Plate | 0 | - |
| Chevy | LUV | 1972 | 1 | Left Rear Panel | 0 | - |
| Datsun | Pickup | 1975 | 1 | Left Rear Panel | 1.0 + LEL | Poor Fit Unit down |
| Chevy | Bel-Air | 1966 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Mazda | - | 1971 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Pickup | - | 1 | - | High | Unit down |
| Chevy | Nova | - | 1 | - | 1.0 + LEL | Unit down |
| VW | - | 1967 | 1 | - | 1.0 + LEL | Unit down |
| VW | - | 1970 | 1 | - | 1.0 + LEL | - |
| Plymouth | Fury | 1972 | 1 | Under License Plate | 1.0 + LEL | Unit down |
| Chevy | Impala | 1967 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Toyota | - | 1970 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Ford | Pinto | 1970 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Malibu | 1972 | 1 | Under License Plate | 1.0 + LEL | Unit down |
| Ford | Pinto | 1973 | 1 | Left Rear Panel | 1.0 + LEL | Unit down |
| Datsun | 1600 | 1970 | 2 | Left Rear Panel | 0 | Self-Serve |
| Chevy | Chevelle | 1970 | 2 | Under License Plate | 0 | Self-Serve |
| Plymouth | Duster | 1974 | 2 | Left Rear Panel | 0 | Self-Serve |
| Ford | Mustang | 1966 | 2 | Rear Panel | 1.0 + LEL | Self-Serve |
| Ford | Pinto | 1972 | 2 | Left Rear Panel | 800 PPM | Self-Serve |
| Ford | Pickup | - | 2 | - | 1.0 + LEL | Poor Fit Self-Serve |
| Dodge | - | 1964 | 2 | Left Rear Panel | 0 PPM | Self-Serve |
| Chevy | Van | 1975 | 2 | - | 1.0 + LEL | Poor Fit Self-Serve |
| Oldsmobile | StaWag | 1971 | 2 | Left Rear Panel | 0 | Self-Serve |
| Ford | StaWag | 1972 | 2 | Left Rear Panel | 0 | Self-Serve |
| - | Pickup | 1970 | 2 | Behind Left Door | 0 | Self-Serve |
| Chevy | Bel-Air | 1974 | 2 | Under License Plate | 0 | Self-Serve |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|-------------|--------------|-------------|--|-------------------------------|---------------------------|---------------------------------|
| Mercury | - | 1967 | 2 | Under License Plate | 0-200 PPM | Self-Serve |
| Ford | LTD | 1973 | 2 | Left Rear Panel | 0 | Self-Serve |
| Datsun | 1600 P/U | 1973 | 2 | Right Rear Panel | 0 | - |
| Dodge | Pickup | 1971 | 2 | Behind Left Door | 0 | Self-Serve |
| Dodge | Dart | 1964 | 2 | Left Rear Panel | 0 | Self-Serve |
| Ford | Mustang | 1968 | 2 | Rear Panel | 0 | Self-Serve |
| Mercury | Capri | 1973 | 2 | Right Rear Panel | 0 | - |
| Dodge | CoronetWag. | 1973 | 2 | Left Rear Panel | 1.0 + LEL | Insufficient Vacuum |
| Ford | Pickup | 1970 | 2 | - | 0 | - |
| Buick | Sta.Wag | 1967 | 2 | - | High | Poor Fit |
| Datsun | - | 1974 | 2 | Right Rear Panel | 0 | - |
| Ford | Mustang II | 1974 | 2 | Left Rear Panel | 0 | Self-Serve |
| Ford | Pickup | 1969 | 2 | Left Rear Panel | 0 | Spit Back At End of Fill |
| Chevy | Step-Van | 1964 | 2 | Right Rear Panel | 0 | - |
| Ford | Maverick | 1971 | 2 | Rear Panel | 0 | - |
| Chevy | Corvette | 1972 | 2 | Above Trunk | 0 | - |
| Datsun | 1600 | 1973 | 2 | Right Rear Panel | 0 | Spit Back at End of Fill |
| Chevy | Pickup | 1972 | 3 | Left Rear Panel | 0 | - |
| Ford | Truck | - | 3 | - | 1.0 + LEL | - |
| Chevy | Pickup | 1973 | 3 | Behind Right Door | 0 | - |
| Chevy | 350 Truck | 1973 | 3 | Below Cab Right Side | 0-100 PPM | Poor Fit |
| Chevy | C/50 | 1968 | 3 | Behind Left Door | 0 | Poor Fit |
| Datsun | Pickup | 1973 | 3 | Right Rear Panel | 0 | - |
| Chevy | Pickup | 1974 | 3 | Behind Left Door | 1.0 + LEL | - |
| Chevy | Pickup | 1968 | 3 | Behind Left Door | 0 | - |
| Chevy | Impala | 1969 | 4 | Under License Plate | 0-600 PPM | - |
| VW | Bus | 1968 | 4 | Left Rear Panel | 0 | - |
| Volvo | Sta.Wag. | 1973 | 4 | Right Rear Panel | 0-300 PPM | - |
| Ford | Pinto | 1972 | 4 | Left Rear Panel | 0 | - |
| BMW | - | 1969 | 4 | Right Rear Panel | 1.0 + LEL | Poor Fit |
| Ford | Pinto | 1970 | 4 | Left Rear Panel | 0 | - |
| Ford | Pinto | 1973 | 4 | Left Rear Panel | 0 | - |
| Volvo | Sta.Wag. | 1971 | 4 | Right Rear Panel | 0 | - |
| VW | Sta.Wag. | 1970 | 4 | Right Front Panel | 0 | - |
| Ford | Fairlane | 1969 | 4 | Under License Plate | 400 PPM | Supply Hose Leaks Gas at Nozzle |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|--------------------|--------------|-------------|--|-------------------------------|---------------------------|-----------------------|
| Ford | Falcon | 1962 | 4 | Left Rear Panel | 0 | - |
| Chevy | Vega Wagon | 1971 | 4 | Right Rear Panel | 0 | - |
| Ford | Mustang | 1968 | 4 | Rear Panel | 0 | - |
| Ford | Pickup | 1973 | 4 | Left Rear Panel | 0 | - |
| VW | Bus | 1971 | 4 | Right Rear Panel | 1.0 + LEL | Poor Fit |
| Opel | Coupe | 1970 | 4 | Right Rear Panel | 0 | - |
| Volvo | Sta.Wag. | 1967 | 4 | Right Rear Panel | 0 | - |
| Toyota | Pickup | 1973 | 4 | Right Mid Panel | 0 | - |
| Chevy | Vega | 1971 | 4 | Under License Plate | 1.0 + LEL | Nozzle Being Repaired |
| Datsun | 1600 | 1973 | 4 | Right Rear Panel | 0 | - |
| Mercury | Capri | 1972 | 4 | Right Front Panel | 1.0 + LEL | - |
| VW | Rabbit | 1975 | 4 | - | 0 | Good Fit |
| VW | Bug | 1968 | 4 | - | 0 | - |
| Pontiac | Sta.Wag. | 1974 | 4 | - | 0 | - |
| VW | Bug | 1974 | 4 | - | 0 | - |
| Datsun | 1200 | - | 4 | Right Rear Panel | 1000 PPM | - |
| Chevy | Chevelle | 1973 | 4 | - | 1.0 + LEL | Poor Fit |
| Ford | Pinto Wagon | 1973 | 5 | Left Rear Panel | 0 | - |
| Chevy | LUV | 1972 | 5 | Left Rear Panel | 0 | - |
| Volvo | Sta.Wag. | 1974 | 5 | Left Rear Panel | 0 | - |
| Buick | Le Sabre | 1973 | 5 | Under License Plate | 0 | - |
| Lincoln | MK IV | 1972 | 5 | Under License Plate | 0 | - |
| VW | Sta.Wag. | 1971 | 5 | Right Front Panel | 0 | - |
| Chevy | El Camino | 1968 | 5 | Left Rear Panel | 0 | - |
| Ford | Fairlane | 1967 | 5 | Left Rear Panel | 0 | - |
| Buick | Regal | 1971 | 5 | - | 0 | - |
| Plymouth | - | 1969 | 5 | - | 0 | - |
| Ford | Pinto Wagon | 1974 | 5 | - | 0 | - |
| Inter- national | - | 1971 | 5 | - | 0 | - |
| Lincoln | Continental | 1974 | 5 | Left Rear Panel | 1.0 + LEL | - |
| Toyota | - | 1971 | 5 | Under License Plate | 0 | - |
| Dodge | Van | 1963 | 5 | Left Rear Panel | 0 | - |
| Chevy | Van | 1974 | 5 | Left Rear Panel | 0 | - |
| Plymouth | Fury | 1968 | 5 | Under License Plate | 0 | - |
| VW | Bug | 1967 | 5 | Right Front Panel | 0 | - |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|-------------|--------------|-------------|--|-------------------------------|---------------------------|---|
| Chevy | Impala | 1964 | 5 | Left Rear Panel | 0 | - |
| Chevy | - | 1965 | 5 | Under License Plate | 0 | - |
| Ford | Bronco | 1970 | 5 | Right Mid Panel | 0 | - |
| Dodge | Sta.Wag. | 1972 | 5 | Under License Plate | 0 | - |
| Chevy | Pickup | 1973 | 5 | Right Mid Panel | 0 | - |
| Ford | Pinto | 1972 | 5 | Left Rear Panel | 0 | - |
| Ford | LTD | 1975 | 6 | Under License Plate | 0-0.2 LEL | - |
| Chevy | El Camino | 1970 | 6 | Left Rear Panel | 1.0 + LEL | - |
| Chevy | Camaro | 1972 | 6 | Under License Plate | 1.0 + LEL | - |
| Ford | Torino | 1973 | 6 | Under License Plate | 1.0 + LEL | - |
| Chevy | El Camino | - | 6 | Left Rear Panel | 1.0 + LEL | Poor Fit |
| Chevy | Sta.Wag. | 1970 | 6 | Left Rear Panel | 0 | - |
| Buick | Riviera | 1966 | 6 | Under License Plate | 1.0 + LEL | Poor Fit |
| Lincoln | MK IV | 1974 | 6 | Left Rear Panel | 0 | - |
| Ford | Pinto | - | 6 | Left Rear Panel | 0 | - |
| Ford | Ranchero | - | 6 | - | 0 | - |
| Dodge | Charger | 1970 | 6 | - | 1.0 + LEL | - |
| Ford | Sta.Wag. | 1973 | 6 | - | 0.2 LEL | - |
| Chevy | Pickup | 1973 | 6 | Right Mid Panel | 0 | - |
| Ford | Granada | 1975 | 6 | - | 0 | - |
| Dodge | Polara | 1972 | 6 | - | 0-600 PPM | - |
| Pontiac | - | 1973 | 6 | - | 0-700 PPM | - |
| Dodge | Van | 1974 | 6 | - | 0 | - |
| Plymouth | - | 1973 | 6 | - | 0-100 PPM | - |
| Chev | Monte Carlo | 1974 | 6 | Under License Plate | - | Readings not taken because of gas spillage |
| GMC | Pickup | 1969 | 6 | - | 0 | - |
| Chev | Pickup | 1975 | 6 | Right Rear Panel | 1.0 + LEL | - |
| Datsun | 610 | 1973 | 6 | Right Rear Panel | 1.0 + LEL | - |
| VW | Bug | 1967 | 6 | Right Front Panel | 0-500 PPM | - |
| Ford | LTD | 1972 | 6 | Left Rear Panel | 1.0 + LEL | - |
| Ford | Pinto | 1970 | 6 | Left Rear Panel | 0 | - |
| Chevy | Van | 1974 | 6 | Left Rear Panel | 1.0 + LEL | - |
| Ford | Pinto | 1973 | 6 | Left Rear Panel | 0-1000 PPM | - |
| Ford | Pickup | 1972 | 6 | Left Rear Panel | 0 | - |
| Chevy | Pickup | 1973 | 7 | Right Side Panel | 0 | - |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|--------------------|--------------|-------------|--|-------------------------------|---------------------------|------------------------------------|
| Pontiac | LeMans | 1966 | 7 | Under License Plate | 0 | - |
| Plymouth | Duster | 1972 | 7 | Left Side Panel | 0 | - |
| Datsun | Pickup | 1972 | 7 | - | 1.0 + LEL | Unit down |
| Cadillac | - | 1974 | 7 | Under License Plate | 400 PPM | Unit down |
| Ford | LTD | 1972 | 7 | Left Rear Panel | 1.0 + LEL | Unit down |
| Ford | LTD | 1970 | 7 | - | 0 | - |
| Inter- national | - | 1968 | 7 | Behind Right Door | 0 | - |
| VW | Bug | 1964 | 7 | Inside Trunk | 0-600 PPM | - |
| Chevy | Camaro | 1968 | 7 | Rear Panel | 1.0 + LEL | Vacuum line not hooked up |
| Ford | Maverick | 1970 | 7 | Rear Panel | 1.0 + LEL | Poor Fit |
| Dodge | Colt | 1975 | 7 | Left Rear Panel | 0 | - |
| Ford | Pickup | 1969 | 7 | Left Rear Panel | 0 | - |
| VW | Bug | 1969 | 7 | Left Front Panel | 0 | - |
| Ford | Van | 1969 | 7 | Left Rear Panel | 1.0 + LEL | Vacuum line not hooked up |
| Ford | Fairlane | 1971 | 7 | Left Rear Panel | - | - |
| Oldsmobile | Sta.Wag. | 1964 | 7 | Left Rear Panel | 100 PPM | - |
| Ford | Mustang | 1969 | 7 | Rear Panel | 1.0 + LEL | Vacuum Line not hooked up |
| Chevy | Chevelle | 1968 | 8 | - | 1.0 + LEL | Unit down |
| Chevy | - | 1957 | 8 | - | 1.0 + LEL | Unit down |
| Ford | Mustang | 1966 | 8 | Rear Panel | 1.0 + LEL | Unit down |
| Oldsmobile | 98 | 1968 | 8 | Under License Plate | 1.0 + LEL | Unit down |
| Ford | Fairlane | 1971 | 8 | Left Rear Panel | 1000 PPM | Unit down |
| Chevy | Camaro | 1968 | 8 | Rear Panel | 0 | - |
| Datsun | - | 1973 | 8 | Right Rear Panel | 0 | - |
| Chevy | - | 1969 | 8 | Under License Plate | 0 | - |
| Dodge | Satellite | 1974 | 8 | Under License Plate | 1.0 + LEL | Unit down |
| Chevy | Chevelle | 1970 | 8 | Under License Plate | 0 | Liquid gas leak at nozzle union |
| Ford | Pickup | 1967 | 8 | Behind Left Door | 0 | - |
| Chevy | Malibu Wag. | 1968 | 8 | Left Rear Panel | 0 | - |
| Datsun | 240Z | 1969 | 8 | Right Rear Panel | 1.0 + LEL | Poor Fit |
| Oldsmobile | - | 1973 | 8 | Under License Plate | 0 | - |
| Dodge | - | 1973 | 8 | Under License Plate | 1.0 + LEL | Unit down |
| Chevy | Monte Carlo | 1974 | 8 | Under License Plate | 1.0 + LEL | Unit down |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|-------------|--------------|-------------|--|-------------------------------|---------------------------|-----------------|
| Opel | 1900 | 1972 | 8 | Right Rear Panel | 1.0 + LEL | Unit down |
| Ford | Van | 1969 | 8 | Left Rear Panel | 1.0 + LEL | Unit down |
| Chevy | - | 1973 | 9 | Under License Plate | 1.0 + LEL | Unit down |
| Ford | Van | 1969 | 9 | Left Rear Panel | 1.0 + LEL | Unit down |
| AMC | Rebel | 1967 | 9 | - | 0 | - |
| Pontiac | Grand Prix | 1969 | 9 | - | 0 | - |
| Honda | Civic | 1974 | 9 | Left Rear Panel | 0 | - |
| Chevy | Pickup | 1968 | 9 | Behind Left Door | 0 | - |
| Fiat | 1200 | 1963 | 9 | - | 0 | - |
| Chevy | Monte Carlo | 1970 | 9 | - | 0 | - |
| Dodge | Sta.Wag. | 1974 | 9 | - | 0 | - |
| Honda | Civic | 1974 | 9 | Left Rear Panel | 1.0 + LEL | Unit down |
| Datsun | B210 | 1973 | 9 | Right Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Vega | 1970 | 9 | Under License Plate | 1.0 + LEL | Unit down |
| Ford | Maverick | 1972 | 9 | Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Monte Carlo | 1973 | 9 | Under License Plate | 1.0 + LEL | Unit down |
| Chrysler | - | 1974 | 9 | Under License Plate | 0 | - |
| Oldsmobile | 98 | 1968 | 9 | Under License Plate | 1.0 + LEL | Poor Fit |
| Ford | Maverick | 1972 | 10 | Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Bel-Air | 1974 | 10 | Under License Plate | 1.0 + LEL | Unit down |
| Ford | Pinto | 1972 | 10 | Left Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Pickup | 1973 | 10 | Right Mid Panel | 1.0 + LEL | Unit down |
| Datsun | 610 | 1973 | 10 | Right Rear Panel | 1.0 + LEL | Unit down |
| Dodge | Colt | 1971 | 10 | Left Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Pickup | 1968 | 10 | Left Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Impala | 1959 | 10 | Under License Plate | 1.0 + LEL | Unit down |
| Mercury | Cougar | 1970 | 10 | Under License Plate | 1.0 + LEL | Unit down |
| Ford | Maverick | 1970 | 10 | Rear Panel | 1.0 + LEL | Unit down |
| Oldsmobile | - | 1972 | 10 | Under License Plate | 1.0 + LEL | Unit down |
| Ford | Mustang | 1968 | 10 | Rear Panel | 1.0 + LEL | Unit down |
| Porsche | 912 | 1970 | 10 | - | 1000+PPM | Unit down |
| Chevy | Impala | 1966 | 10 | - | 1000+PPM | Unit down |
| Mercury | Capri | 1971 | 10 | - | 1000+PPM | Unit down |
| Buick | - | 1973 | 10 | Under License Plate | 1.0 + LEL | Unit down |
| Pontiac | Sta.Wag. | 1972 | 10 | - | High at end of fill | Unit down |
| Toyota | Pickup | 1974 | 10 | Left Mid Panel | 1.0 + LEL | Unit down |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|--------------------|--------------|-------------|--|-------------------------------|---------------------------|-----------------|
| Ford | Galaxie | 1965 | 11 | Left Rear Panel | 0 | Self-Serve |
| Mercury | Comet | 1964 | 11 | - | 0 | Self-Serve |
| Ford | 3/4 Ton P/U | 1966 | 11 | - | 1000+PPM | Self-Serve |
| Ford | Ranchero | 1975 | 11 | - | 0 | Self-Serve |
| Ford | Galaxie | 1966 | 11 | - | 0 | Self-Serve |
| Inter- national | Travelall | 1969 | 11 | - | 0 | Self-Serve |
| Jeep | - | 1973 | 11 | - | 0 | Self-Serve |
| Pontiac | GTO | 1967 | 11 | - | 0 | Self-Serve |
| Buick | Riviera | 1966 | 11 | Under License Plate | 0 | Self-Serve |
| Mercury | Cougar | 1970 | 11 | Under License Plate | 0 | Self-Serve |
| Chevy | Nova | 1973 | 11 | - | 0 | Self-Serve |
| Dodge | Futura | 1972 | 11 | - | 0 | Self-Serve |
| Buick | Le Sabre | 1970 | 11 | - | 0 | Self-Serve |
| VW | Bus | 1971 | 11 | Right Rear Panel | 0 | Self-Serve |
| Ford | 3/4 Ton P/U | 1970 | 11 | - | 0 | Self-Serve |
| Chevy | Sta.Wag. | 1972 | 11 | - | 0 | Self-Serve |
| Oldsmobile | 98 | 1974 | 11 | - | 0 | - |
| Chevy | Nova | 1970 | 11 | Under License Plate | 0 | - |
| Ford | Falcon | - | 11 | - | 0 | - |
| Chevy | Van | 1970 | 11 | - | 0 | - |
| Ford | - | 1970 | 11 | Left Rear Panel | 0 | Self-Serve |
| Chevy | Camaro | 1973 | 11 | Under License Plate | 0 | Self-Serve |
| Chevy | Pickup | 1974 | 11 | Behind Door | 0 | - |
| Toyota | Pickup | 1969 | 11 | Left Rear Panel | 0 | - |
| Chevy | Nova Wagon | 1968 | 11 | Left Rear Panel | 0 | Poor Fit |
| Mercury | Cougar | 1970 | 11 | Under License Plate | 0 | - |
| Ford | Maverick | 1972 | 11 | Rear Panel | 0 | - |
| VW | Bug | 1970 | 11 | Right Front Panel | 0 | - |
| Pontiac | Ventura | 1972 | 11 | Under License Plate | 0 | Self-Serve |
| AMC | Javalin | 1968 | 11 | Under License Plate | 0 | Self-Serve |
| Dodge | Pickup | 1974 | 11 | Behind Left Door | 0 | Self-Serve |
| Chevy | Nova | 1972 | 11 | Under License Plate | 0 | Self-Serve |
| Datsun | - | 1968 | 11 | Right Rear Panel | 0 | Self-Serve |
| Buick | Skylark | 1972 | 11 | Under License Plate | 0 | Self-Serve |
| VW | Bus | 1969 | 11 | Right Rear Panel | 0 | Self-Serve |
| Chevy | Impala | 1964 | 11 | Left Rear Panel | 0 | Self-Serve |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|--------------------|--------------|-------------|--|-------------------------------|---------------------------|--|
| Plymouth | - | 1966 | 11 | Under License Plate | 0-200 PPM | Self-Serve |
| Datsun | Pickup | 1973 | 12 | Right Rear Panel | 0-1.0 + LEL | High HC Observation at end of fill |
| Ford | Ranchero | 1967 | 12 | - | 0 | - |
| Fiat | 128 | 1973 | 12 | - | 0 | Poor fit must be hand held |
| Datsun | 240Z | 1973 | 12 | Right Rear Panel | 0-1000 PPM | Bad Seal |
| Chevy | Monte Carlo | 1972 | 12 | Under License Plate | 0-800 PPM | - |
| Dodge | Charger | 1966 | 12 | - | 0.6 LEL | - |
| Ford | Pinto | 1971 | 12 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| VW | - | 1964 | 12 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Ford | Falcon | 1967 | 12 | Rear Panel | 1.0 + LEL | Self-Serve |
| Chevy | Nova | 1965 | 12 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Triumph | TR6 | 1968 | 12 | Behind Rear Window | 1.0 + LEL | Self-Serve |
| Ford | Falcon | 1970 | 12 | Rear Panel | 1.0 + LEL | Self-Serve |
| Ford | Pickup | 1969 | 12 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Dodge | Satellite | 1974 | 12 | Under License Plate | 1.0 + LEL | Poor fit |
| Opel | 1900 | 1972 | 12 | Right Rear Panel | 1.0 + LEL | Self-Serve |
| Buick | Riviera | 1971 | 12 | Under License Plate | 0 | Self-Serve |
| Mazda | Pickup | 1974 | 12 | Left Side Panel | 1.0 LEL | Self-Serve |
| Chevy | Impala | 1972 | 12 | Under License Plate | 1.0 + LEL | Self-Serve |
| Ford | Maverick | 1973 | 12 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Inter- national | Pickup | 1954 | 12 | Behind Left Door | 1.0 + LEL | Self-Serve |
| Cadillac | - | 1970 | 12 | Under License Plate | 0-400 PPM | - |
| Ford | Pinto | 1971 | 12 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Ford | LTD | 1969 | 12 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Ford | Mustang | 1968 | 13 | Rear Panel | 1.0 + LEL | Self-Serve |
| Datsun | Sta.Wag. | 1971 | 13 | Right Rear Panel | 1.0 + LEL | Poor fit |
| Ford | Courier | 1971 | 13 | Left Mid Panel | 1.0 + LEL | Self-Serve |
| Fiat | Coupe | 1971 | 13 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Chevy | LUV | 1972 | 13 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Datsun | 1600 | 1973 | 13 | Right Rear Panel | 1.0 + LEL | Self-Serve Poor Fit |
| Ford | LTD | 1973 | 13 | Left Rear Panel | 1.0 + LEL | - |
| GMC | Duravan | 1973 | 13 | Left Rear Panel | 1.0 + LEL | - |
| Ford | LTD | 1973 | 13 | Left Rear Panel | 1.0 + LEL | - |
| Buick | Electra | 1964 | 13 | Left Rear Panel | 1.0 + LEL | High HC observations appeared to be caused by nozzle |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|-------------|--------------|-------------|--|-------------------------------|---------------------------|--|
| Chrysler | Imperial | 1970 | 13 | Under License Plate | 1.0 + LEL | Self-Serve |
| Mercury | Capri | 1972 | 13 | Right Front Panel | 1.0 + LEL | Self-Serve |
| Dodge | Dart | 1964 | 13 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Pontiac | Le Mans | 1974 | 13 | Under License Plate | 1.0 + LEL | - |
| Dodge | Dart | 1974 | 13 | Left Rear Panel | 0-200 PPM | - |
| Ford | LTD | 1972 | 13 | Left Rear Panel | 1.0 + LEL | Self-Serve Poor Fit |
| Chevy | Sta.Wag. | 1970 | 13 | Left Rear Panel | 1.0 + LEL 0 PPM | Self-Serve Attendant Serve |
| Ford | Pinto | 1974 | 13 | Left Rear Panel | 0-200 PPM | Self-Serve |
| Ford | Mustang | 1968 | 13 | Rear Panel | 0 | Self-Serve |
| Ford | Falcon | 1972 | 13 | - | 0 | - |
| Chevy | 6/50 Truck | 1971 | 13 | - | 1.0 + LEL | - |
| Datsun | 1200 P/U | 1965 | 13 | - | 0-1000 PPM | - |
| Chevy | El Camino | 1963 | 13 | - | 1000 + PPM | - |
| Chevy | Camaro | 1967 | 13 | - | 0 | Good fit |
| Ford | Pinto | 1971 | 13 | Left Rear Panel | 0 | Good fit |
| Pontiac | Catalina | 1966 | 13 | Under License Plate | 1000 PPM | Poor Fit |
| Ford | Falcon | 1964 | 14 | Left Rear Panel | - | Poor Fit must be hand held |
| Chrysler | Le Baron | 1968 | 14 | - | 0.2 LEL | Good fit |
| VW | "Thing" | 1973 | 14 | - | 0 | Hand held |
| Ford | Thunderbird | 1968 | 14 | - | 1.0 + LEL | - |
| Chevy | Van | 1975 | 14 | - | 1000 + PPM | - |
| Alfa Romeo | - | 1973 | 14 | - | 1000 + PPM | - |
| VW | Dasher | 1974 | 14 | - | 1000 + PPM | - |
| Ford | Pinto | 1970 | 14 | Left Rear Panel | 1.0 + LEL | Self-Serve nozzle fell out of car did not shut off |
| Dodge | Sta.Wag. | 1973 | 14 | Left Rear Panel | 1.0 + LEL | Poor fit |
| Ford | Custom P/U | 1974 | 14 | Right Rear Panel | 1.0 + LEL | Self-Serve |
| MGB | - | 1968 | 14 | Right Rear Panel | 1.0 + LEL | Self-Serve |
| Datsun | Pickup | 1971 | 14 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Ford | Mustang | 1969 | 14 | Rear Panel | 1.0 + LEL | Self-Serve |
| Plymouth | - | 1968 | 14 | Left Rear Panel | 0 | - |
| Plymouth | Sta.Wag. | 1965 | 14 | Left Rear Panel | 1.0 + LEL | Self-Serve |
| Mercedes | - | 1971 | 14 | Under License Plate | 1.0 + LEL | Poor Fit |
| Chevy | Sta.Wag. | 1970 | 14 | Left Rear Panel | 0 | Self-Serve |
| VW | Bus | 1969 | 14 | Right Rear Panel | 1.0 + LEL | Self-Serve |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|--------------------|---------------------|-------------|--|-------------------------------|---------------------------|-----------------|
| Toyota | Corona | 1974 | 14 | Left Rear Panel | 0-200 PPM | Self-Serve |
| Mercury | Capri | 1974 | 14 | - | 1.0 + LEL | - |
| Toyota | Corrolla | 1972 | 14 | Left Side Panel | 1.0 + LEL | - |
| Chev. | Vega | 1971 | 14 | Under License Plate | 1.0 + LEL | Spit Back |
| Ford | LTD | 1973 | 14 | Left Rear Panel | 1.0 + LEL | - |
| Ford | - | 1972 | 14 | Under License Plate | 0-300 PPM | - |
| Oldsmobile | 88 | 1968 | 14 | Under License Plate | 1.0 + LEL | Self-Serve |
| Dodge | Pickup | 1974 | 14 | Left Mid Panel | 1.0 + LEL | Self-Serve |
| Toyota | 1900 | 1968 | 14 | Under License Plate | 0-200 PPM | - |
| Chev. | Corvette | 1966 | 14 | Above Trunk | 1.0 + LEL | Poor Fit |
| Ford | Van | 1970 | 14 | Left Rear Panel | 0 | - |
| Inter- national | CO 1600 | 1969 | 15 | - | 1.0 + LEL | - |
| Ford | Fairlane | 1972 | 15 | - | 1000 + PPM | - |
| Jeep | - | 1975 | 15 | - | 0-1000 PPM | - |
| Inter- national | Truck | 1969 | 15 | Right Panel | 1.0 + LEL | Poor Vacuum |
| Dodge | 4 Ton Truck | 1970 | 15 | Right Rear Panel | 1.0 + LEL | Poor Vacuum |
| Chevy | Truck | 1968 | 15 | Right Side Panel | 1.0 + LEL | Poor Vacuum |
| AMC | - | 1973 | 15 | Right Front Panel | 1.0 + LEL | Poor Vacuum |
| Jeep | - | 1968 | 15 | Rear Panel | 1.0 + LEL | Poor Vacuum |
| GM | Truck | 1972 | 15 | Rear Panel | 0.6 LEL | Unit down |
| Chevy | 1 Ton Truck | 1968 | 15 | Right Rear Panel | 1.0 + LEL | Unit down |
| AMC | Truck | 1971 | 15 | Rear Panel | 1.0 + LEL | Unit down |
| AMC | Truck | 1971 | 15 | Rear Panel | 1.0 + LEL | Unit down |
| Inter- national | 1/2 Ton Step-Van | 1969 | 15 | Right Side Panel | 1.0 + LEL | Unit down |
| Inter- national | Truck | 1968 | 15 | Left Rear Panel | 1.0 + LEL | Unit down |
| Jeep | Truck | 1968 | 15 | Rear Panel | 1.0 + LEL | Unit down |
| Jeep | Truck | 1970 | 15 | Right Rear Panel | 1.0 + LEL | Unit down |
| Jeep | Truck | 1968 | 15 | Right Rear Panel | 1.0 + LEL | Unit down |
| Jeep | Truck | 1975 | 15 | Right Rear Panel | 1.0 + LEL | Unit down |
| Jeep | Truck | 1975 | 15 | Right Rear Panel | 1.0 + LEL | Unit down |
| Ford | Torino | 1973 | 15 | Under License Plate | 1.0 LEL | Poor Fit |
| Ford | 5 Ton Truck | 1974 | 15 | - | 1.0 LEL | Poor Fit |
| Inter- national | Loadstar | 1968 | 15 | - | 0 | - |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|--------------------|--------------|-------------|--|-------------------------------|---------------------------|---------------------------------|
| Inter- national | 1310 Truck | 1973 | 15 | - | 0-100 PPM | - |
| Jeep | - | 1971 | 15 | - | 0-400 PPM | - |
| Ford | 1½ Ton Truck | 1971 | 15 | - | 0 | - |
| Jeep | - | 1975 | 15 | - | 0 | - |
| Dodge | - | 1974 | 16 | - | 1.0 + LEL | - |
| Dodge | - | 1974 | 16 | - | 0.1 LEL | - |
| Dodge | - | 1974 | 16 | - | 0 | - |
| Dodge | - | 1974 | 16 | - | 1.0 + LEL | - |
| Dodge | - | 1974 | 16 | - | 100 PPM | - |
| Dodge | Polara | 1974 | 16 | Under License Plate | 0-200 PPM | - |
| Dodge | Polara | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Polara | 1974 | 16 | Under License Plate | 0-300 PPM | - |
| Dodge | Monaco | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | 1.0 LEL just before shut-off |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | 1.0 LEL just before shut-off |
| Dodge | - | 1974 | 16 | - | 0.1 LEL | - |
| Dodge | - | 1974 | 16 | - | 300 PPM | - |
| Dodge | - | 1974 | 16 | - | 0 | - |
| Dodge | - | 1974 | 16 | - | 0.2 LEL | - |
| Dodge | Monaco | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 16 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 16 | Rear Panel | 0 | - |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|--------------------|----------------|-------------|--|-------------------------------|---------------------------|-----------------|
| Cadillac | - | 1973 | 18 | Under License Plate | 0 | - |
| Chevy | Corvette | 1969 | 18 | Top of Trunk | 1.0 + LEL | Poor Fit |
| Ford | Pinto | 1971 | 18 | Left Rear Panel | 0 | - |
| Datsun | 1600 Sportscar | 1967 | 18 | Right Rear Panel | 50-100 PPM | - |
| Datsun | 510 | 1968 | 18 | Right Rear Panel | 0 | - |
| VW | Bus | 1974 | 18 | Right Rear Panel | 0 | - |
| Chevy | Impala | 1974 | 18 | Under License Plate | 0 | - |
| Ford | Pinto | 1971 | 18 | Left Rear Panel | 0 | - |
| Ford | LTD | 1973 | 18 | Left Rear Panel | 0 | - |
| MG | - | 1970 | 18 | Right Rear Panel | 0 | - |
| Chevy | LUV | 1969 | 18 | Left Side Panel | 0 | - |
| Cadillac | - | 1973 | 18 | Under License Plate | 1.0 + LEL | - |
| Ford | LTD | 1973 | 18 | Left Rear Panel | 0 | - |
| Chevy | Chevelle | 1975 | 18 | - | 0 | - |
| VW | Bug | 1974 | 18 | - | 0 | - |
| VW | Bug | 1969 | 18 | - | 0 | - |
| Oldsmobile | Cutlass | 1973 | 18 | - | 0 | - |
| AMC | Hornet Wagon | 1974 | 18 | - | 0 | - |
| Dodge | Van | 1971 | 18 | - | 0 | - |
| Chevy | Chevelle | 1974 | 18 | - | 0 | - |
| VW | Bug | 1964 | 18 | - | 0 | - |
| Ford | 350 Pickup | 1972 | 18 | - | 0 | - |
| Chevy | Chevelle | 1974 | 18 | - | 0 | - |
| Chevy | Vega | 1971 | 18 | Under License Plate | 0 | - |
| Pontiac | - | 1968 | 18 | - | 1.0 + LEL | Poor Fit |
| Chevy | LUV | 1972 | 18 | Left Rear Panel | 0 | - |
| Opel | 1900 | 1972 | 18 | Right Rear Panel | 0 | - |
| Toyota | - | 1969 | 18 | Left Rear Panel | 0 | - |
| Ford | Mustang | 1969 | 18 | Rear Panel | 0 | - |
| Cadillac | Coupe DeVille | 1973 | 18 | Under License Plate | 0 | - |
| Chevy | Pickup | 1970 | 18 | Right Mid Panel | 0-200 PPM | - |
| VW | - | 1972 | 18 | Right Front Panel | 1.0 + LEL | Poor Fit |
| Ford | Pinto | 1970 | 18 | Left Rear Panel | 0 | - |
| Plymouth | Road Runner | 1969 | 19 | Under License Plate | 1.0 + LEL | No Vacuum |
| Inter- national | 5 Ton Truck | 1970 | 19 | Below Cab Left Side | 1.0 + LEL | No Vacuum |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|-------------|----------------|-------------|--|-------------------------------|---------------------------|---------------------------|
| Chevy | Monte Carlo | 1974 | 19 | Under License Plate | 1.0 + LEL | No Vacuum |
| Cadillac | - | 1974 | 19 | Under License Plate | 1.0 + LEL | Unit down |
| VW | Bus | 1968 | 19 | Right Rear Panel | 1.0 + LEL | Unit down |
| Datsun | 1600 P/U | 1969 | 19 | Left Mid Panel | 1.0 + LEL | Unit down |
| Ford | Falcon | 1964 | 19 | Left Rear Panel | 1.0 + LEL | Unit down |
| Rambler | - | 1964 | 19 | Left Rear Panel | 1.0 + LEL | Unit down |
| Dodge | Dart | 1974 | 19 | Left Rear Panel | 1000 + PPM | Unit down |
| VW | Bus | 1972 | 19 | - | 100 PPM | Unit down |
| Audi | Fox | 1974 | 19 | - | 1.0 + LEL | Unit down |
| Mazda | Coupe | 1972 | 19 | Left Rear Panel | 1.0 + LEL | Unit down |
| Ford | Maverick | 1970 | 19 | Rear Panel | 1.0 + LEL | Unit down |
| Opel | 1900 | 1973 | 19 | Right Rear Panel | 1.0 + LEL | Unit down |
| Datsun | Coupe | 1972 | 19 | Right Rear Panel | 1.0 + LEL | Unit down |
| Cadillac | - | 1973 | 20 | Rear Panel | 1.0 + LEL | Unit down |
| Ford | Mustang II | 1974 | 20 | Left Rear Panel | 1.0 + LEL | Unit down |
| Chevy | Corvette | 1969 | 20 | Above Trunk | 1.0 + LEL | Poor Fit Unit down |
| Chevy | Chevelle Wagon | 1974 | 20 | Left Rear Panel | 1.0 + LEL | Unit down |
| Ford | Maverick | 1972 | 20 | Rear Panel | 1.0 + LEL | Vacuum lines disconnected |
| Chevy | Impala | 1973 | 20 | Under License Plate | 1.0 + LEL | Vacuum lines disconnected |
| Chevy | 1/2 Ton P/U | 1971 | 20 | - | - | Nozzle does not fit |
| Chevy | Nova | 1973 | 20 | - | 0 | - |
| Rambler | StaWag | 1966 | 20 | - | 1000 + PPM | - |
| Chevy | Camaro | 1966 | 20 | - | 0 | - |
| Toyota | Corrolla | 1974 | 20 | Left Rear Panel | 0 | - |
| Toyota | Pickup | 1974 | 20 | Left Mid Panel | 0 | - |
| Mercury | Montego | 1974 | 20 | - | 0 | - |
| Mazda | RX-3 | 1972 | 20 | Left Rear Panel | 0.8 LEL | - |
| Ford | Galaxie | 1965 | 20 | Left Rear Panel | 1.0 + LEL | Unit down |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|-------------|---------------|-------------|--|-------------------------------|---------------------------|------------------------------|
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 100 PPM | - |
| Dodge | Polara | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1974 | 21 | Under License Plate | 0 | - |
| Dodge | Monaco | 1975 | 21 | - | 0 | - |
| Dodge | Polara | 1973 | 21 | - | 0 | - |
| Dodge | Monaco | 1974 | 21 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 21 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 21 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 21 | Rear Panel | 0 | 1,0 + LEL at end of fill |
| Dodge | Monaco | 1974 | 21 | Rear Panel | 0 | - |
| Dodge | Monaco | 1974 | 21 | Rear Panel | 0 | - |
| Pontiac | Le Mans | 1965 | 22 | Under License | 1000 + PPM | Tow Hitch caused poor fit |
| Dodge | Coronet | 1968 | 22 | Under License Plate | 0 | - |
| Chev. | Malibu | 1973 | 22 | - | 1000 + PPM | Poor Fit |
| Plymouth | Belvedere | 1964 | 22 | - | 100 PPM | - |
| Dodge | Coronet Wagon | 1965 | 22 | - | 0 | - |
| Chev. | Monte Carlo | 1970 | 22 | Under License Plate | 0 | - |
| Datsun | - | 1974 | 22 | Right Rear Panel | 0 | - |
| Dodge | Coronet | 1968 | 22 | Under License Plate | 0 | - |
| Dodge | Coronet Wagon | 1973 | 22 | Left Rear Panel | 0 | - |
| Chev. | Vega | 1972 | 22 | Under License Plate | 0 | - |
| Ford | Ranchero | 1971 | 22 | Left Rear Panel | 0 | - |
| Ford | Maverick | 1971 | 22 | Rear Panel | 0 | - |
| Dodge | Coronet Wagon | 1973 | 22 | Left Rear Panel | 0-800 PPM | Poor Fit |
| Ford | Granada | 1975 | 22 | - | 0 | Good Fit |
| Buick | Electra | 1967 | 23 | Under License Plate | 1.0 + LEL | Poor Vacuum |
| Ford | Mustang | 1968 | 23 | Rear Panel | 1.0 + LEL | Poor Vacuum |
| Ford | Fairlane | 1964 | 23 | Rear Panel | 1.0 + LEL | Poor Vacuum |
| Ford | Falcon | 1968 | 23 | Rear Panel | 1.0 + LEL | Poor Fit Poor Vacuum |
| Dodge | - | 1973 | 23 | Under License Plate | 1.0 + LEL | Poor Vacuum |
| Plymouth | - | 1966 | 23 | Left Rear Panel | 0 | Spit back at end of fill |
| Ford | Ranchero | 1974 | 23 | Left Rear Panel | 0 | Spit back at end of fill |
| Ford | Torino | 1972 | 23 | Under License Plate | 0 | - |

AUTOMOBILES TESTED (cont)

| <u>MAKE</u> | <u>MODEL</u> | <u>YEAR</u> | <u>STATION NUMBER WHERE TESTED</u> | <u>FILL NECK LOCATION</u> | <u>HC OBSERVATION</u> | <u>COMMENTS</u> |
|-------------|---------------|-------------|--|-------------------------------|---------------------------|----------------------|
| VW | Bug | 1966 | 23 | Inside Trunk | 1.0 + LEL | Poor Fit |
| Ford | Pinto Wagon | 1973 | 23 | Left Rear Panel | 0 | - |
| VW | Bus | 1967 | 23 | Right Rear Panel | 0 | - |
| Dodge | StaWag | 1973 | 24 | Left Rear Panel | 1.0 + LEL | Poor Vacuum |
| Mercedes | - | 1969 | 24 | Under License Plate | 0-600 PPM | Poor Vacuum |
| Ford | Pinto | 1970 | 24 | Left Rear Panel | 1.0 + LEL | Poor Vacuum |
| VW | Bug | 1970 | 24 | Right Front Panel | 1.0 + LEL | Poor Vacuum |
| Mazda | RX2 | 1972 | 24 | Left Rear Panel | 1.0 + LEL | Poor Vacuum |
| Chevy | Van | 1973 | 24 | Left Rear Panel | 0 | Poor Vacuum |
| Cadillac | Coupe DeVille | 1974 | 24 | Under License Plate | 0 | Poor Vacuum |
| Chevy | Camaro | 1974 | 24 | Under License Plate | 1.0 + LEL | Poor Vacuum |
| Volvo | 142 Sedan | 1970 | 24 | Right Rear Panel | 1.0 + LEL | Poor Vacuum |
| Rambler | Nash | 1967 | 24 | Rear Panel | 1.0 + LEL | Poor Vacuum |
| Ford | LTD | 1973 | 24 | Left Rear Panel | 1.0 + LEL | Poor Vacuum |
| Datsun | StaWag | 1967 | 24 | Under License Plate | 1.0 + LEL | Poor Fit Poor Vacuum |
| Ford | Pinto | 1970 | 24 | Left Rear Panel | 1.0 + LEL | Poor Vacuum |
| VW | Bug | 1965 | 24 | Inside Trunk | 200 PPM | Poor Vacuum |
| Chevy | Vega | 1971 | 24 | Under License Plate | 0 | Poor Vacuum |
| Jaguar | XKE | 1971 | 24 | Left Rear Panel | 1.0 + LEL | Poor Vacuum |
| Cadillac | DeVille | 1974 | 24 | Under License Plate | 1.0 + LEL | Poor Vacuum |

APPENDIX C
Measured Operational Parameters

I. INTERMARK SYSTEMS

| <u>Date of Visit</u> | <u>Station Location</u> | <u>Comments</u> |
|----------------------|-------------------------|--|
| 7/1/75 | Sears | Bladder level indicator read 1/8 capacity, pressure = 0.64" H ₂ O. |
| 7/9/75 | Sears | Bladder down, pressure = 0.45" H ₂ O, compressor came on when level indicator read 1/8 capacity, pressure = 2" H ₂ O. |
| 7/2/75 | Gemco | Pressure = 1.5" H ₂ O when bladder level indicator read 1/8-3/8 capacity, pressure = 0.35" H ₂ O when level indicator read 1/16 - 1/8 capacity and compressor turned off, pressure = 1.4" H ₂ O when level indicator read just under 1/8 capacity and compressor started. |
| 7/9/75 | Gemco | Bladder in down position, pressure = 0.45" H ₂ O, pressure = 1.4" H ₂ O when level indicator read 1/8 capacity. |
| 7/30/75 | Gemco | Bladder in full up position, pressure = 7.5" H ₂ O. |
| 7/3/75 | Encinitas | Pressure = 2.4" H ₂ O, corresponding bladder level not known because level indicator does not work. |
| 7/10/75 | Encinitas | Pressure = 0" H ₂ O, processing unit down. |
| 7/10/75 | Carmel Valley | Pressure = 0" H ₂ O, processing unit down. |

II. PROCESS PRODUCTS SYSTEMS & TEMPERATURE DATA

| | | |
|---------|-------------|--|
| 6/18/75 | Waring Road | Refrigeration unit starts at 4" H ₂ O stops at 0.5" H ₂ O. |
| 6/30/75 | Waring Road | Refrigeration unit starts at 3.5 - 3.8" H ₂ O, stops at 0.5" H ₂ O |
| 7/8/75 | Waring Road | Refrigeration unit starts at 4.5" H ₂ O, stops at 0.5" H ₂ O |

II. PROCESS PRODUCTS SYSTEMS & TEMPERATURE DATA (cont)

| <u>Date of Visit</u> | <u>Station Location</u> | <u>Comments</u> |
|----------------------|----------------------------|---|
| 7/16/75 | Waring Road | Refrigeration unit starts at 4.5" H ₂ O, stops at 0.5" H ₂ O |
| 7/22/75 | Waring Road | Refrigeration starts at 4.2" H ₂ O, stops at 0.2" H ₂ O |
| 7/29/75 | Waring Road | Refrigeration starts at 4.5" H ₂ O, stops at 1" H ₂ O. |
| 6/19/75 | Friars & Frazee | Condensate return = 12F, no pressure data |
| 6/23/75 | Friars & Frazee | Refrigeration starts at 1.1" H ₂ O, stops at 0.5" H ₂ O |
| 6/26/75 | Friars & Frazee | Condensate return = 22F, no pressure data |
| 7/3/75 | Friars & Frazee | Refrigeration starts at 1" H ₂ O, stops at 0.5" H ₂ O. |
| 7/9/75 | Friars & Frazee | Condensate return = 30F, refrigeration starts at 1.1" H ₂ O, stops at 0.3" H ₂ O |
| 7/17/75 | Friars & Frazee | Refrigeration starts at 1" H ₂ O, stops at 0.5" H ₂ O |
| 7/22/75 | Friars & Frazee | Condensate return = 30F, refrigeration starts at 1.1" H ₂ O, stops at 0.5" H ₂ O. |
| 7/30/75 | Friars & Frazee | Condensate return = 40F, refrigeration starts at 1" H ₂ O, stops at 0.5" H ₂ O |
| 7/15/75 | Clairmont & Clairmont Mesa | Tank pressure at 0.6" H ₂ O, processing unit down |
| 7/22/75 | Clairmont & Clairmont Mesa | Tank pressure 0" H ₂ O, unit down. |
| 7/9/75 | Bubble Machine | Tank pressure = 3.5" H ₂ O, unit down. |

III. CLEAN AIR ENGINEERING SYSTEMS

| | | |
|---------|-------------|--|
| 6/25/75 | Tierrasanta | Manifold pressure = 3" H ₂ O. |
| 6/30/75 | Tierrasanta | Manifold pressure = 3.5" H ₂ O. |
| 7/8/75 | Tierrasanta | Manifold pressure = 3.5" H ₂ O (low pressure adjusted to reduce sooting, according to Clean Air). |
| 7/22/75 | Tierrasanta | Manifold pressure = 3.2" H ₂ O while burning. |
| 7/29/75 | Tierrasanta | Manifold pressure = 3.3" H ₂ O |

III. CLEAN AIR ENGINEERING SYSTEMS (cont)

| <u>Date of Visit</u> | <u>Station Location</u> | <u>Comments</u> |
|----------------------|-------------------------|---|
| 6/26/75 | Highway Patrol, S.D. | Manifold pressure = 5.5" H ₂ O |
| 7/2/75 | Highway Patrol, S.D. | 15" H ₂ O when just vapor recovery blower on, 5.3" H ₂ O when burner pump starts, when burner pump stopped pressure went to -3" H ₂ O but leveled to zero after 2 min. |
| 7/10/75 | Highway Patrol, S.D. | Manifold pressure = 5" H ₂ O. |
| 7/15/75 | Highway Patrol, S.D. | Manifold pressure = 5.5" H ₂ O while burning. |
| 7/28/75 | Highway Patrol, S.D. | Manifold pressure = 5.3" H ₂ O |
| 6/30/75 | Rocky Home Dairy | 14.4" H ₂ O when vapor collection blower on, pressure went to 6.8" H ₂ O when burner on. |
| 7/8/75 | Rocky Home Dairy | Pressure goes to 15" H ₂ O when vapor collection blower starts, as burner starts pressure decreases to 6.5" H ₂ O. |
| 7/16/75 | Rocky Home Dairy | Manifold Pressure = 6.8" H ₂ O while burning |
| 7/22/75 | Rocky Home Dairy | Manifold Pressure = 6.3" H ₂ O. |
| 7/28/75 | Rocky Home Dairy | Manifold Pressure = 4.2" H ₂ O. |
| 7/3/75 | Highway Patrol, Onside | 5.5" H ₂ O while burner pump on, 15" H ₂ O before burner activated. |
| 7/10/75 | Highway Patrol, Onside | 15" H ₂ O before burner pump on, 5-5½" H ₂ O after burner pump started. |
| 7/18/75 | Highway Patrol, Onside | Manifold pressure = 5.3" H ₂ O |
| 7/31/75 | Highway Patrol, Onside | Manifold pressure = 4.0" H ₂ O |

IV. HIRT SYSTEM DATA

| | | |
|---------|-----------|--|
| 7/10/75 | Oceanside | Compressed air starts when tank pressure = -0.58" H ₂ O, small burner starts when tank pressure = -0.58" H ₂ O, |
|---------|-----------|--|

IV. HIRT SYSTEM DATA (cont)

| <u>Date of Visit</u> | <u>Station Location</u> | <u>Comments</u> |
|----------------------|-------------------------|--|
| | | compressed air and burners stop when tank pressure = $-0.65'' \text{ H}_2\text{O}$ (large burner starts when tank pressure = $-0.1'' \text{ H}_2\text{O}$, this was not observed but information was supplied by Hirt). |
| 7/15/75 | Oceanside | Compressed air starts when tank pressure = $-0.61'' \text{ H}_2\text{O}$, small burner starts when pressure = $-0.61'' \text{ H}_2\text{O}$. |
| 7/31/75 | Oceanside | Compressed air and small burner start when tank pressure = $-0.58'' \text{ H}_2\text{O}$, both stop when tank pressure = $-0.61'' \text{ H}_2\text{O}$. |

V. ENVIRONICS SYSTEMS

| | | |
|---------|----------------|---|
| 7/1/75 | Parkway Texaco | Reactor Temp. = 73F (?), unit down. |
| 7/9/75 | Parkway Texaco | Reactor Temp. = 1065F. |
| 7/16/75 | Parkway Texaco | Reactor starts at 1290F, carbon regeneration pump deactivates when temp. reaches 740F. |
| 7/29/75 | Parkway Texaco | Pressure switch at $1.6'' \text{ H}_2\text{O}$, $2.6'' \text{ H}_2\text{O}$ when vapor collection blower starts then back to $1.6'' \text{ H}_2\text{O}$. |
| 7/2/75 | Post Office | Reactor Temp. at 848F when burner pump came on, then went down to 760F. |
| 7/10/75 | Post Office | Reactor temp at 872F before any gas fillups. |
| 7/17/75 | Post Office | Processing unit down, reactor temp = 635F. |
| 7/21/75 | 6th & Robinson | Pressure switch opened at $1.5'' \text{ H}_2\text{O}$. |

APPENDIX D

Automobiles with Fillnecks Poorly Fit by Nozzles

AUTOMOBILES WITH FILLNECKS POORLY FIT BY NOZZLES

| <u>Maker</u> | <u>Model</u> | <u>Year</u> | <u>Location of Fillneck</u> |
|--------------|----------------|-------------|-----------------------------|
| BMW | - | 1969 | Right Rear Side |
| Buick | Riviera | 1966 | Under License Plate |
| Buick | Sta. Wag. | 1967 | |
| Chevy | Malibu | 1973 | |
| Chevy | Corvette | 1966 | On Top Of Trunk |
| Chevy | El Camino | - | Left Rear Side |
| Chevy | Nova Wagon | 1968 | Left Rear Side |
| Chevy | Corvette | 1969 | On Top Of Trunk |
| Chevy | 1/2 Ton Pickup | 1971 | (Nozzle Did Not Fit) |
| Chevy | Van | 1975 | |
| Chevy | Chevelle | 1973 | |
| Chevy | 350 Truck | 1973 | Below Cab On Right Side |
| Chevy | L/50 Truck | 1968 | Behind Left Cab Door |
| Chevy | Corvette | 1969 | On Top Of Trunk |
| Datsun | Sta. Wag. | 1971 | Right Rear Side |
| Datsun | 1600 | 1973 | Right Rear Side |
| Datsun | 240z | 1973 | Right Rear Side |
| Datsun | 240z | 1969 | Right Rear Side |
| Datsun | Sta. Wag. | 1967 | Under License Plate |
| Datsun | Pickup | 1975 | Left Rear Side |
| Dodge | Coronet Wagon | 1973 | On Left Rear Side |
| Dodge | Satellite | 1974 | Under License Plate |
| Dodge | Sta. Wag. | 1973 | Left Rear Side |

AUTOMOBILES WITH FILLNECKS POORLY FIT BY NOZZLES (Continued)

| <u>Maker</u> | <u>Model</u> | <u>Year</u> | <u>Location of Fillneck</u> |
|--------------|--------------|-------------|--|
| Dodge | Polara | 1967 | Under License Plate |
| Fiat | 128 | 1973 | |
| Ford | LTD | 1972 | Left Rear Side |
| Ford | Falcon | 1964 | Left Rear Side |
| Ford | Pickup | - | |
| Ford | Maverick | 1970 | At Rear |
| Ford | Torino | 1973 | Under License Plate |
| Ford | 5 Ton Truck | 1974 | |
| Ford | Falcon | 1968 | At Rear |
| Mercedes | - | 1971 | Under License Plate |
| Oldsmobile | 98 | 1968 | Under License Plate |
| Pontiac | Le Mans | 1965 | Under License Plate. Tow Hitch Hindered Fit. |
| Pontiac | Catalina | 1966 | Under License Plate |
| Pontiac | - | 1968 | |
| VW | Bus | 1971 | Right Rear Side |
| VW | Bug | 1966 | Inside Trunk |
| VW | - | 1972 | Right Front Side |

Poor Fits can be due to obstructions such as towing hitches, pop-up gas caps, anti-syphon devices, door hatches over fill necks, etc.

APPENDIX E
Observations with EPA Hydrocarbon Detectors

OBSERVATIONS WITH EPA HYDROCARBON DETECTORS

I. Clean Air Engineering Systems

| <u>Date of Visit</u> | <u>Station Location</u> | <u>HC Detector Reading</u> | <u>Comments</u> |
|----------------------|-------------------------|----------------------------|--|
| 6/10/75 | Rocky Home Dairy | 10.6 Hr | Start time on detector was 10.6 Hr, detector installed was #245-3 504-3 Probe #5 (Latching Type) |
| 6/18/75 | Rocky Home Dairy | 10.6 Hr | |
| 6/19/75 | Rocky Home Dairy | No Reading | |
| 6/25/75 | Rocky Home Dairy | 10.6 Hr | |
| 6/30/75 | Rocky Home Dairy | 10.6 Hr | |
| 7/8/75 | Rocky Home Dairy | 10.6 Hr | |
| 7/16/75 | Rocky Home Dairy | 10.6 Hr | Recorded as 0.6 Hr on data sheet, but detector will not run in reverse and not enough hours had passed to complete a total revolution of the timer, so reading was assumed to be 10.6 Hr |
| 7/22/75 | Rocky Home Dairy | No Reading | |
| 7/28/75 | Rocky Home Dairy | 10.6 Hr | Recorded as 0.6 Hr |
| 6/17/75 | Highway Patrol, S.D. | 0.5 Hr | Start time on detector was 0.5 Hr, detector installed was #245-2, 504-1, Probe #2 (Non-latching Type) |
| 6/26/75 | Highway Patrol, S.D. | No Reading | |
| 7/2/75 | Highway Patrol, S.D. | 0.5 Hr | |
| 7/10/75 | Highway Patrol, S.D. | 0.5 Hr | |
| 7/15/75 | Highway Patrol, S.D. | 0.5 Hr | |
| 7/28/75 | Highway Patrol, S.D. | 0.5 Hr | |

OBSERVATIONS WITH EPA HYDROCARBON DETECTORS (Continued)

II. Environics Systems

| <u>Date of Visit</u> | <u>Station Location</u> | <u>HC Detector Reading</u> | <u>Comments</u> |
|----------------------|-------------------------|----------------------------|--|
| 6/11/75 | Midway Post Office | 0.2 Hr | Start time on detector was 0.2 Hr, detector installed was #245-3 504-1, Probe #6 (Latching Type) |
| 6/24/75 | Midway Post Office | 306.5 Hr | Read at 0830 and reset with start at 306.6 Hr |
| 6/27/75 | Midway Post Office | 306.6 Hr | Upon visit found main power to processing unit off. Reason unknown. |
| 7/2/75 | Midway Post Office | 306.6 Hr | Blower failure observed during visit. |
| 7/10/75 | Midway Post Office | 306.6 Hr | Blower still not repaired |
| 7/17/75 | Midway Post Office | 306.6 Hr | Blower still not repaired |
| 7/31/75 | Midway Post Office | 306.6 Hr | Blower repaired |
| 6/10/75 | Parkway Texaco | 0.35 Hr | Start time on detector was 0.35 Hr, detector installed was #245-2, 504-1, Probe #3 (Non-latching Type) |
| 6/17/75 | Parkway Texaco | No Reading | |
| 6/18/75 | Parkway Texaco | 0.40 Hr | |
| 6/26/75 | Parkway Texaco | 0.45 Hr | |
| 7/1/75 | Parkway Texaco | 0.80 Hr | |
| 7/9/75 | Parkway Texaco | 1.6 Hr | |
| 7/16/75 | Parkway Texaco | 2.4 Hr | |
| 7/29/75 | Parkway Texaco | 2.6 Hr | |

OBSERVATIONS WITH EPA HYDROCARBON DETECTORS (Continued)

III. PROCESS PRODUCTS SYSTEMS

| <u>Date of Visit</u> | <u>Station Location</u> | <u>HC Detector Reading</u> | <u>Comments</u> |
|----------------------|-------------------------|----------------------------|---|
| 6/19/75 | Friars & Frazee | 0.3 Hr | Start time on detector was 0.3 Hr, detector installed was #245-2, 504-2, Probe #1 (Latching Type) |
| 6/23/75 | Friars & Frazee | 0.3 Hr | |
| 6/26/75 | Friars & Frazee | 0.3 Hr | |
| 7/3/75 | Friars & Frazee | 0.3 Hr | |
| 7/9/75 | Friars & Frazee | 0.3 Hr | |
| 7/17/75 | Friars & Frazee | No Reading | HC Detector disconnected by ARB so they could do their own testing |
| 7/22/75 | Friars & Frazee | No Reading | |
| 7/30/75 | Friars & Frazee | 0.3 Hr | |
| 6/17/75 | College Car Wash | No Reading | Processing unit down Detector installed was #245-3, 504-2, Probe #4 (Non-latching Type) |
| 6/18/75 | College Car Wash | No Reading | Processing unit down |
| 7/2/75 | College Car Wash | No Reading | Processing unit down |
| 7/11/75 | College Car Wash | 0.2 Hr | Processing unit down Found blown fuse in detector |
| 7/17/75 | College Car Wash | No Reading | Processing unit down |
| 7/23/75 | College Car Wash | No Reading | Processing unit down |
| 7/30/75 | College Car Wash | No Reading | Processing unit down |

| TECHNICAL REPORT DATA (Please read instructions on the reverse before completing) | | |
|---|--|--|
| 1. REPORT NO. EPA-450/3-76-001 | 2. | 3. RECIPIENT'S ACCESSION NO. |
| 4. TITLE AND SUBTITLE Reliability Study of Vapor Recovery Systems at Service Stations | 5. REPORT DATE March 1976 | 6. PERFORMING ORGANIZATION CODE |
| 7. AUTHOR(S) R. J. Bryan R. L. Norton L. G. Wayne | 8. PERFORMING ORGANIZATION REPORT NO. | |
| 9. PERFORMING ORGANIZATION NAME AND ADDRESS Pacific Environmental Services, Inc. 1930 14th Street Santa Monica, California 90404 | 10. PROGRAM ELEMENT NO. | 11. CONTRACT/GRANT NO. 68-02-1405 Task Order No. 2 |
| 12. SPONSORING AGENCY NAME AND ADDRESS U. S. Environmental Protection Agency Research Triangle Park, North Carolina 27711 | 13. TYPE OF REPORT AND PERIOD COVERED Control Systems Evaluation | 14. SPONSORING AGENCY CODE |
| 15. SUPPLEMENTARY NOTES | | |
| 16. ABSTRACT <p>A study was conducted of the operational reliability of vapor recovery systems at gasoline service stations in San Diego County, California. Periodic inspections at 24 stations were conducted to examine the condition of these systems, to determine their operational status, and to check for detectable gasoline vapor losses from control equipment.</p> <p>The study demonstrated that capture of vapors at the vehicle was more effective with vacuum-assisted systems than with vapor balance systems. However, the reliability of the vacuum-assisted systems was not good in general although there was substantial variation depending upon the type of unit.</p> | | |
| 17. KEY WORDS AND DOCUMENT ANALYSIS | | |
| a. DESCRIPTORS Air Pollution Gasoline Marketing Service Station Vapor Recovery | b. IDENTIFIERS/OPEN ENDED TERMS Air Pollution Control Stationary Sources Mobile Sources Hydrocarbons | c. COSATI Field/Group |
| 18. DISTRIBUTION STATEMENT Unlimited | 19. SECURITY CLASS (This Report) Unclassified | 21. NO. OF PAGES |
| | 20. SECURITY CLASS (This page) Unclassified | 22. PRICE |

INSTRUCTIONS

1. **REPORT NUMBER**
Insert the EPA report number as it appears on the cover of the publication.
2. **LEAVE BLANK**
3. **RECIPIENTS ACCESSION NUMBER**
Reserved for use by each report recipient.
4. **TITLE AND SUBTITLE**
Title should indicate clearly and briefly the subject coverage of the report, and be displayed prominently. Set subtitle, if used, in smaller type or otherwise subordinate it to main title. When a report is prepared in more than one volume, repeat the primary title, add volume number and include subtitle for the specific title.
5. **REPORT DATE**
Each report shall carry a date indicating at least month and year. Indicate the basis on which it was selected (*e.g., date of issue, date of approval, date of preparation, etc.*).
6. **PERFORMING ORGANIZATION CODE**
Leave blank.
7. **AUTHOR(S)**
Give name(s) in conventional order (*John R. Doe, J. Robert Doe, etc.*). List author's affiliation if it differs from the performing organization.
8. **PERFORMING ORGANIZATION REPORT NUMBER**
Insert if performing organization wishes to assign this number.
9. **PERFORMING ORGANIZATION NAME AND ADDRESS**
Give name, street, city, state, and ZIP code. List no more than two levels of an organizational hierarchy.
10. **PROGRAM ELEMENT NUMBER**
Use the program element number under which the report was prepared. Subordinate numbers may be included in parentheses.
11. **CONTRACT/GRANT NUMBER**
Insert contract or grant number under which report was prepared.
12. **SPONSORING AGENCY NAME AND ADDRESS**
Include ZIP code.
13. **TYPE OF REPORT AND PERIOD COVERED**
Indicate interim final, etc., and if applicable, dates covered.
14. **SPONSORING AGENCY CODE**
Leave blank.
15. **SUPPLEMENTARY NOTES**
Enter information not included elsewhere but useful, such as: Prepared in cooperation with, Translation of, Presented at conference of, To be published in, Supersedes, Supplements, etc.
16. **ABSTRACT**
Include a brief (*200 words or less*) factual summary of the most significant information contained in the report. If the report contains a significant bibliography or literature survey, mention it here.
17. **KEY WORDS AND DOCUMENT ANALYSIS**
 - (a) **DESCRIPTORS** - Select from the *Thesaurus of Engineering and Scientific Terms* the proper authorized terms that identify the major concept of the research and are sufficiently specific and precise to be used as index entries for cataloging.
 - (b) **IDENTIFIERS AND OPEN-ENDED TERMS** - Use identifiers for project names, code names, equipment designators, etc. Use open-ended terms written in descriptor form for those subjects for which no descriptor exists.
 - (c) **COSATI FIELD GROUP** - Field and group assignments are to be taken from the 1965 COSATI Subject Category List. Since the majority of documents are multidisciplinary in nature, the Primary Field/Group assignment(s) will be specific discipline, area of human endeavor, or type of physical object. The application(s) will be cross-referenced with secondary Field/Group assignments that will follow the primary posting(s).
18. **DISTRIBUTION STATEMENT**
Denote releasability to the public or limitation for reasons other than security for example "Release Unlimited." Cite any availability to the public, with address and price.
19. & 20. **SECURITY CLASSIFICATION**
DO NOT submit classified reports to the National Technical Information service.
21. **NUMBER OF PAGES**
Insert the total number of pages, including this one and unnumbered pages, but exclude distribution list, if any.
22. **PRICE**
Insert the price set by the National Technical Information Service or the Government Printing Office, if known.